Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

		Expire:					
5.	Lease	Design	ation	and	Serial	Nυ.	

MM.	2	7	U,	2	/,	

	NM-27024
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir Use "APPLICATION FOR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well Oil Well Well Other	8. Well Name and No.
2. Name of Operator	Mesa Twin Mounds
Walsh Engineering & Production Corp. 3. Address and Telephone No.	9. API Well No. 30-045-25751
204 N. Auburn Farmington, New Mexico 87401 505 327-4892	10. Field and Pixel, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Jindes Gallup Dakota
790'FNL, 990'FWL Section 30, T30N, R14W	11. County or Parish, State San Juan, N.M.
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	DRT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	٧
Notice of Intent	Change of Plans
Recompletion	New Construction
Subsequent Republic NAR 1 1933 Plugging Back	Non-Routine Fracturing
L Casing Repair	Water Shat Off
Final Abandonment Solice CON. DIV. Altering Casing See Below	Conversion to Injection Dispose Water
DIST. 3	(Note: Report results of multiple completion on Wes- Completion of Recompletion Report and Log form (
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of start give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
	larch 1, 1993
This is a request for approval of an extension of shut in of M for this well. Previous request was approved until March 1, 1 Conditions concerning the necessity of the shut in have not es	larch 1, 1993, 993. SEEB PH
This is a request for approval of an extension of shut in of M for this well. Previous request was approved until March 1, 1 Conditions concerning the necessity of the shut in have not es changed since the approval of the previous request.	larch 1, 1993. 993. SEEB PH
This is a request for approval of an extension of shut in of M for this well. Previous request was approved until March 1, I Conditions concerning the necessity of the shut in have not eschanged since the approval of the previous request. THIS APPROVAL PROPER MAR 0 1 1994 FOR: WALSH ENGR. & PROD. CORP. 14. Thereby certify that the foregoing is rue and correct Engineer	larch 1, 1993 993. 35 EB BLAVE Sentia My BLAVE NM 4 2/16/93
This is a request for approval of an extension of shut in of M for this well. Previous request was approved until March 1, 1 Conditions concerning the necessity of the shut in have not es changed since the approval of the previous request. THIS APPROVAL PRES MAR 0 1 1994 FOR: WALSH ENGR. & PROD. CORP. 14. I hereby cently that the foregoing is the and correct Signed Landau Control of the Title Engineer	larch 1, 1993 993. 35 EB BLAVE Sentia My BLAVE NM 4 2/16/93

*See Instruction on Reverse Side

or representations as to any matter within its jurisdiction.



WALSH

ENGINEERING & PRODUCTION CORP.

Petroleum Engineering Consulting Lease Management Contract Pumping 3001 Northridge Drive P.O. Drawer 419 Farmington, New Mexico 87401 (505) 327-4892

March 1, 1988

RECEIVED

MAR 02 1988

Mr. Ron Fellows, Area Manager Bureau of Land Management 1235 La Plata Highway Farmington, New Mexico 87401

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA

REF: Walsh Engineering & Production Corporation
Mesa Twin Mounds 30, No. 1
NW/4 Section 30-T30N-R14W
San Juan County, New Mexico
Lease No. NM-27024

Dear Mr. Fellows:

This is a request for approval of shut in of the above-referred-to well on a long term basis.

The reasons for this request are as follows:

- 1. The tubing and rods are parted, therefore, the well is not in pumping condition.
- 2. The well cannot be repaired at this time due to:
 - A. The well is involved in the filing of Bankruptcy by Lobo Production.
 - B. There is no clear documentation as to ownership of working interest by investors in the well.
- 3. It is now apparent that the situation concerning ownership of working interest by investors will not be resolved in the near future.

Thank you for your consideration and if you have any questions, please do not hesitate to call upon me.

Very truly yours,

Ewell N. Walsh, P.E.

President

THIS APPROVAL EXPIRES 3/3/89

enw:rr cc: Dick Ledbetter, President First National Bank

Robert L. Finch, Trustee

Frank Chavez, NMOCD, Aztec, N.M.

MAR 03 1988