

F

30-045-26071

8-24-84

NSL-1872

F. Loc. 2110/N; 830/W Elev. 5740 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W' _____ Sx. Int. _____ @ _____ W' _____ Sx. Pr. _____ @ _____ W' _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS	NITD X	Well Log	TEST DATA							
Ojo Alamo	C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.	
Kirtland	C-104	Electric Log								
Fruitland		C-122								
Pictured Cliffs	Ditr	Dfa								
Chacra	Datr	Dac								
Cliff House	info #1 in 31-31N-13W NSL-1872 NSP R-2046 Acres 321.99									
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

P
o
o

Basin Dak. Co. SJ 56 T 30N R 13W U/F Oper. Robert L. Bayless Les. Stribling Com No. 1E

Stribling Com #1E

F-6-30N-13W

ROBERT L. BAYLESS

Caller Service 4104
Farmington, New Mexico 87401

FEB 20 1986

CERTIFICATE--REVIEW RECEIPT REQUESTED

Robert L. Keyless
P.O. Box 101
Farmington, NM 87401

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) for well No. 1-7
Irrigation Co., SE/4NW/4 sec. 6, T. 30 N., R. 13 E., San Juan County, New
Mexico, tract SE-G0007-A.

As discussed with Mrs. Lulu Lerger of your Company on February 12, 1986, the
subject APD is rescinded and returned due to drilling not being commenced
within one year of the approval date.

You are required to request surface rehabilitation instructions from this
office if construction activities occurred on the referenced drill site. If
this office does not receive comment within 15 days, we will presume that no
construction occurred. Later discovery that construction activities have in
fact occurred, will result in an assessment.

Sincerely,


for James Miller
Area Manager

Enclosure

cc:
NR000

RECEIVED
FEB 24 1986
C. J. Miller
100

ABANDONED LOCATION