Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEME		Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	NDRY NOTICES AND REPORTS s form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such	back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL CAS WELL WELL	OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	•		8. FARM OR LEASE NAME
1 FE 300 DIL CO. 3. ADDRESS OF OPERATOR			9. WBLL NO.
438130 4. LOCATION OF WELL	# 5		
See also space 17 be	10. FIELD AND POOL, OR WILDCAT		
At surface 5E/4 NW/4			VERDE GALLAP 11. SBC., T., R., M., OR BLK. AND
52117	1277	,	SURVEY OR AREA
			SEC5T3ON RISW
14. PERMIT NO.	15. ELEVATIONS (Show whether	, , , , , , , , , , , , , , , , , , , ,	12. COUNTY OR PARISH 13. STATE
16.			SANSUAN N.M.
	Check Appropriate Box To Indicate		ther Vata
TEST WINES STORE]
TEST WATER SHUT-	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	BEPAIRING WELL ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other)	of multiple completion on Well
17. DESCRIBE PROPOSED (OR COMPLETED OPERATIONS (Clearly state all perting	Completion or Recomple	etion Report and Log form.)
nent to this work.)	i wen is directionally drined, give subsuriace los	cations and measured and true vertica	depths for all markers and zones perti-
_	S SACK CEMENT PL		,
3701 20	LE WITH 4.2 PP6 1	arua pair'	
FILL 140.			
SPOT 2	S SACK CEMENT PL	16 AT 100.	TO SURFIXE
•			
			0.10
			92 J
			AR UN
		JUN 1032	RECEIVED BLM JUN-4 AMII FARMINGTON
		man	NO N 3<
		Section of the sectio	
		Wall o	AMII: 18
			RECEIVED BLM 92 JUN -4 AMII: 18 019 FARMINGTON, N.M.
			-

SIGNED 77 2002 / 67 TITLE DOUNER

OATE 10-5-91

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TITLE DOUNER

DATE 10-5-91

AS AMENDED

JUN 04 1992

*See Instructions on Reverse Side

AREA MANAGE

UNITED STATES DEPARTMENT OF THE INTERIOR

The contract the state of the contract of the

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 5 Malco Copple

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Wwk Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):
 - 1) Bring Gallup plug up to 2550 to cover formation top
 - 2) place sustace plug from 176 (50' below sustace casing shoe) to sustace.

Office Hours: 7:45 a.m. to 4:30 p.m.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6#/gal slurry weight is to be used when using class B neat cement or when CaCl₂ is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.