UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



GAS Tribe Name 7. Unit Agreement Name 2. Name of Operator WAR 1 9 1999 OIL & GAS COMPANY				BLM		
1. Type of Well GAS OIL & GAS COMPANY OIL & GAS C		Sundry Notices and Reports on Wells			PM 1:06	
OIL & GAS COMPANY 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1735' FNL, 1775' FEL, Sec. 27, T-30-N, R-10-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Recompletion Notice of Intent Recompletion Non-Routine Fracturing Casing Repair Subsequent Report Pinal Abandonment Altering Casing Conversion to Injection X Other - Tubing Repair 13. Describe Proposed or Completed Operations 3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg				C	SF-078200B If Indian, All. or	
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1735' FNL, 1775' FEL, Sec. 27, T-30-N, R-10-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Motice of Intent Recompletion Notice of Intent Recompletion Abandonment Recompletion Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - Tubing Repair 13. Describe Proposed or Completed Operations 3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg		- 5 0		ICENSTA	Unit Agreement Name	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool 1735' FNL, 1775' FEL, Sec. 27, T-30-N, R-10-W, NMPM Blanco Mesaverde 11. County and State San Juan Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent Abandonment Recompletion New Construction X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Altering Casing Conversion to Injection X Other - Tubing Repair 13. Describe Proposed or Completed Operations 3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. Co to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg			**************************************	Asan a second		
PO Box 4289, Farmington, NM 87499 (505) 326-9700 30-045-26426 4. Location of Well, Footage, Sec., T, R, M 1735' FNL, 1775' FEL, Sec. 27, T-30-N, R-10-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Motice of Intent Abandonment Recompletion Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Other - Tubing Repair 13. Describe Proposed or Completed Operations 3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7 RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg		SOMES	& GAS COMPANY			
4. Location of Well, Footage, Sec., T, R, M 10. Field and Pool 1735' FNL, 1775' FEL, Sec. 27, T-30-N, R-10-W, NMPM 11. County and State San Juan Co, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Abandonment Recompletion Recompletion Non-Routine Fracturing Casing Repair Casing Repair Altering Casing Conversion to Injection X Other - Tubing Repair 13. Describe Proposed or Completed Operations 3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg		-		DIT. 3 9.	API Well No.	
Type of Submission Notice of Intent Abandonment Recompletion New Construction Non-Routine Fracturing Casing Repair Altering Casing Altering Casing Conversion to Injection X Other - Tubing Repair 13. Describe Proposed or Completed Operations 3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg				PM	Field and Pool Blanco Mesaverde County and State	
Notice of IntentAbandonmentChange of Plans					DATA	
3-1-99 MIRU. ND WH. NU BOP. TOOH w/2 3/8" tbg, tbg stuck. RU wireline. Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg		_ Notice of Intent _ Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Pla New Construct Non-Routine F Water Shut of Conversion to	ion racturing f	
Ran freepoint. TOOH. SDON. 3-2-99 TIH w/tbg cutter, chemical cut @ 4470'. TOOH w/cutter. RD wireline. TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg	13. Des	scribe Proposed or Compl	leted Operations			
TOOH w/portion of 2 3/8" tbg. TIH w/overshot, engage fish @ 4468'. Jarred fish & worked free. TOOH w/overshot & remaining tbg. SDON. 3-3-99 TIH w/3 7/8" cone bit & watermelon mill. Unload well, tag up @ 4478'. Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg		Ran freepoint.	TOOH. SDON.			
Mill through hard scale @ 4478-4499'. TIH, tag up @ 5376'. Unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH w/bit & mill. SDON. 3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg	3 - 3	TOOH w/portion Jarred fish &	of 2 3/8" tbg. TIH w worked free. TOOH w/c	/overshot, engag overshot & remain	e fish @ 4468'. ing tbg. SDON.	
3-4-99 TIH w/7" RBP, set @ 1600'. TOOH. ND BOP. Changed out tbg heads & csg valves, PT secondary seal to 1500 psi, OK. NU BOP. TIH to top of RBP	J .	Mill through h well & est cir	nard scale @ 4478-4499' cc. CO to PBTD @ 5414'	. TIH, tag up @	5376'. Unload	
Latch RBP & TOOH. TIH, unload well & est circ. CO to PBTD @ 5414'. Circ hole clean. TOOH. TIH w/163 jts 2 3/8" 4.7# J-55 tbg, set @ 530 ND BOP. NU WH. RD. Rig released.	3 - 4					
14. I hereby certify that the foregoing is true and correct.	14./ I h	ereby certify that the	foregoing is true and	correct.	 	
Signed / All hull (Title Regulatory Administrator Date 3/12/99 vkh		May Shall becc	<i>*</i>			
(This space for Federal or State Office use) APPROVED BYTitle RECORD CONDITION OF APPROVAL, if any:	APPROVED	ВУ		AGCEPT		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.