

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

REPORT TO BE SUBMITTED  
WITHIN 90 DAYS OF THE DATE OF  
ISSUE (See instructions on re-  
verse side)

Form 3160-5 (Rev. 10/81-0135)  
Expires August 31, 1985

6. LEASE DESIGNATION AND SERIAL NO.

SF-078387-A

7. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR  
Amoco Production Company

8. FARM OR LEASE NAME

Kernaghan B

3. ADDRESS OF OPERATOR  
P.O. Box 800, Rm. 1846, Denver, CO 80201

9. WELL NO.

#6

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

10. FIELD AND POOL, OR WILDCAT

Basin Fruitland Coal Gas

1280' FNL, 1800' FEL

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

11. BNC, F, H, M, OR BLC AND SURVEY OF AREA

Sec. 29-T31N-R8W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, OR, etc.)

6594' KB

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF   
FRACTURE TREAT   
SHOOT OR ACIDIZE   
REPAIR WELL   
(Other)

FULL OR ALTER CASING   
MULTIPLE COMPLETE   
ABANDON\*   
CHANGE PLANS

WATER SHUT-OFF   
FRACTURE TREATMENT   
SHOOTING OR ACIDIZING   
(Other) Amendment to APD

REPAIRING WELL   
ALTERING CASING   
ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Please be advised of the following changes for the above referenced well.  
Also please note the corrected elevation above.

Formation Tops:	Marker	Depth	Elevation
	Fruitland	3181'	+3413'
	Ignacio Seam	3284'	+3310'
	Cottonwood Seam	3364'	+3230'
	Cahn Seam	3425'	+3169'
	Pictured Cliffs	3471'	+3123'

Total Depth: 3727'

7" Intermediate Casing Point: 3254'

ACCEPTED FOR RECORD

AUG 15 1989

FARMINGTON RESOURCE AREA

BY [Signature]

18. I hereby certify that the foregoing is true and correct

SIGNED J. L. Hampton

TITLE Admin. Supv.

DATE 6/6/89

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side