Form 3160-5 (June 1990)

representations se to any matter within its jurisdiction.

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

 D 00.g			
•	· = 1	170207	- Λ

SUNDRY NO	TICES AND REPORTS	ELSELVE	SF-07838	7-A
Do not use this form for prop Use "APPLIC	osels to drill or to deepen or reentrates ATION FOR PERMIT - " for such pickosal	teent Esevol	. If Indian, Allottee or Tribe Name	
		ANZ 41994	7. If Unit or CA, Agreement Design	nation
		CON. DIV.		
1. Type of Well		DIST. 3	8, Well Name and No.	
Oil Ges Other	Attention:		Kernaghan /B/ #7	
2. Name of Operator Amoco Production Company	Kelly Stea	irns	9, API Well No.	_
3. Address and Telephone No.	(3)	03) 830-4457	3004527	
P.O. Box 800, Denver, Colored	o 80201		Basin Fruitlar	
4. Location of Well (Footage, Sec., T., R., M., or		<b>.</b>	11. County or Parish, State	
1440'FNL 1040'FE	Sec. 30 T 31N R 8V	<b>'V</b>	San Juan	New Mexico
CUTCK APPROPR	IATE BOX(s) TO INDICATE NA	TURE OF NOTICE, R	EPORT, OR OTHER D	ATA
TYPE OF SUBMISSION	IATE BOXIS, TO INDICE.	TYPE OF ACTION		
Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Recavit	Note: Repo	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water on Report and Log form.	Well Completion or
13. Describe Proposed or Completed Operations	(Clearly state all pertinent details, and give pertinent date to vertical depths for all markers and zones pertinent to this	s, including estimated date of starting	g any proposed work . If well is direct	ctionally drilled, give
MIRUSU 12/16/93. BLOW DAND ALL PRESS EQUIP TO PKR. TOH. LAY DOWN PKR FROM 3135' TO 3250'. PIC 3312'. CLEAN OUT FROM 3 BRIDGES AT 3300' AND 33 BRIDGE @ 3301'. PUSH TH NATURAL. FLOW WELL TH SWIVAL AND BREAK CIRC FROM 3250' TO 3368'. THE CLEAN OUT FROM 3168' TO STACK AND BOP'S. SNUB 3102'.PULLED BLANKING I	DOWN WELL THRU BLOOIE LINES. THE 2500 PSI HIGH AND 250 PSI LOW. A PICK UP MILLTOOTH BIT AND F-NIPCK UP CSG SHOE @ 3164'. TIH. TAG 3250' TO 3312'. TIH. CLEAN OUT FROM 3221' TO 3302 STATE OF TO 3312' AND EASILY CLEANED OUT. FLOW TO 3312' AND CLEAN OUT FROM BLOOIE LINES TO BLEED OFF PRE @ SHOE. TIH. TAG UP @ 3281'. CLE H. BREAK CIRC @ SHOE. TIH. TAG UP TO 3368'. TIH. CLEAN OUT BRIDGES IN TBG AND LAND TBG END @ 3145 PLUG FROM F-NIPPLE AT 3102'. SHU	LL TST GOOD. OPEN BY PLE. TIH. UNLOAD HOL UP @ 3212'. CLEAN OU OM 3250' TO 3368'. TO '. CLEAN OUT FROM 31 OW WELL AND STABILIZ M 3312' TO 3368'. TOP SS AND CLEAN UP NAT AN OUT FROM 3281' TO @ 3300' AND CLEAN @ 3300' AND 3312'.NI WITH BAKER 2.75 IN	E @ 3157'.CLEAN OUT JT FROM 3212' TO IH TO SHOE AND PREP 87' TO TD. HAD ZE PRESSURE. TIH. TAG I. SURGE WELL OUTAL.TIH PICK UP OUT TO 3312'. CLEAN OUT OUT TO 3312'.TIH. PPLE UP SNUBBING F-NIPPLE AT	SIVED
14. I hereby certify that the foregoing is true and Signed	tana Tith	Business A	nalyst	01-12-1994
(This space for Federal or State office use)			WUEPTEDF	OR RECORL
	Titk		Date	
Approved by  Conditions of approvel, if any:			IAN1	8 1955
	s for any person knowingly and willfully to make to any de	partment or agency of the United St	ates any false, ficticious, or frauduler	nt statements or
Title 18 U.S.C. Section 1001, makes it a critic	eliction		FARM!NGIGN:	MSTRIGT OFFICE