	FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990 5. Lease Designation and Serial No.
Use "APPLICATION FOR PERMIT" for such proposals MAY 2001 SUBMIT IN TRIPLICATE C	NM-03358
SUBMIT IN TRIPLICATE SUBMIT IN TRIPLICATE 1. Type of Well: oil well gas well X 2. Name of Operator: Devon Energy Corporation 3. Address of Operator: 3300 N. Butler Avenue, Suite 211, Farmington, NM 87401 4. Location of Well: (Footage, Sec., T., R., M., or Survey Description) 1310' FSL, 1080' FWL, Section 11, T31N, R7W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF SUBMISSION Abandonment Recompletion Plugging Back Casing Repair Final Abandonment Notice Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give postarting any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE 1. Type of Well: oil well gas well X 2. Name of Operator: 3. Address of Operator: 3. Address of Operator: 4. Location of Well: (Footage, Sec., T., R., M., or Survey Description) 1310' FSL, 1080' FWL, Section 11, T31N, R7W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF A X Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give presturing any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 popen hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	TAGULIA CA A TA DOLLA
1. Type of Well: 2. Name of Operator: 3. Address of Operator: 3. Address of Operator: 3. Address of Operator: 4. Location of Well: (Footage, Sec., T., R., M., or Survey Description) 1310' FSL, 1080' FWL, Section 11, T31N, R7W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF SUBMISSION X. Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Final Abandonment Notice Altering Casing X. Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pustarting any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.) Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	7. If Unit or CA, Agmt. Design.: Northeast Blanco Unit
2. Name of Operator: 3. Address of Operator: 3. Address of Operator: 3. 300 N. Butler Avenue, Suite 211, Farmington, NM. 87401 4. Location of Well: (Footage, Sec., T., R., M., or Survey Description) 1310' FSL, 1080' FWL, Section 11, T31N, R7W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF Abandonment Recompletion Subsequent Report Plugging Back Casing Repair Final Abandonment Notice Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give per starting any proposed work. If well is directionally drilled, give subsurface locations and measured and tru pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	Well Name and No.:
3. Address of Operator: 3300 N. Butler Avenue, Suite 211, Farmington, NM 87401 4. Location of Well: (Footage, Sec., T., R., M., or Survey Description) 1310' FSL, 1080' FWL, Section 11, T31N, R7W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF X Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Final Abandonment Notice Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pe starting any proposed work. If well is directionally drilled, give subsurface locations and measured and tru pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	N.E.B.U. #442
4. Location of Well: (Footage, Sec., T., R., M., or Survey Description) 1310' FSL, 1080' FWL, Section 11, T31N, R7W 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF Abandonment Recompletion Plugging Back Casing Repair Final Abandonment Notice Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give per starting any proposed work. If well is directionally drilled, give subsurface locations and measured and tru pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	9. API Well No.:
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION X Notice of Intent Subsequent Report Final Abandonment Notice Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco TOTHER OF A Subsequent Report Subsequent Report Plugging Back Casing Repair Altering Casing Completion or Reco (Note: Report result Completion or Reco starting any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	30-045-27569
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF A X Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give perstarting any proposed work. If well is directionally drilled, give subsurface locations and measured and true pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 persopen hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight work estimate: 22 days) and surge well during the night.	10. Field & Pool/Exploratory Area:
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, TYPE OF SUBMISSION TYPE OF A X Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give perstarting any proposed work. If well is directionally drilled, give subsurface locations and measured and true pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 persopen hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight work estimate: 22 days) and surge well during the night.	Basin Fruitland Coal
TYPE OF SUBMISSION X Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pe starting any proposed work. If well is directionally drilled, give subsurface locations and measured and tru pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	11. County or Parish, State:
TYPE OF SUBMISSION X Notice of Intent Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pe starting any proposed work. If well is directionally drilled, give subsurface locations and measured and tru pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 ps open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	San Juan, New Mexico
Abandonment Recompletion Plugging Back Casing Repair	, OR OTHER DATA
Subsequent Report Subsequent Report Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Reco 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give per starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	ACTION
Subsequent Report Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Record starting any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	Change of Plans
Subsequent Report Plugging Back Casing Repair Altering Casing X Other: CBM Re-C (Note: Report result Completion or Record starting any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight wo estimate: 22 days) and surge well during the night.	New Construction
	Non-Routine Fracturing
Final Abandonment Notice Altering Casing X Other: CBM Re-C (Note: Report result Completion or Record 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight work estimate: 22 days) and surge well during the night.	
X Other: CBM Re-C (Note: Report result Completion or Reconstanting any proposed work. If well is directionally drilled, give subsurface locations and measured and truspertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight work estimate: 22 days) and surge well during the night.	Water Shut-Off
(Note: Report result Completion or Recoil 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give perstarting any proposed work. If well is directionally drilled, give subsurface locations and measured and truspertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight work estimate: 22 days) and surge well during the night.	Conversion to Injection
Completion or Reconstruction of Reconstruction o	Cavitation
 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give postarting any proposed work. If well is directionally drilled, give subsurface locations and measured and trupertinent to this work.)* Devon Energy proposes to clean out and remove 5 ½" liner. Pressure test 7" casing to 500 per open hole and remove near well bore coal material. Re-install 5 ½" liner. Use a daylight work estimate: 22 days) and surge well during the night. 14. Thereby certify that the foregoing is true and correct. 	Its of multiple completion on Well
1 /11	ue vertical depths for all markers and zones osi. Under-ream open hole. Re-cavitate
(This space for Federal or State office use) Approved by Title	Date: 4-27-01 MAY 10

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency or the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.