UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notice	ces and Reports on Wells [1: 32
Type of Well GAS	5. Lease Number SF-079037 6. If Indian, All. or Tribe Name
	7. Unit Agreement Name
Name of Operator	PEGERMA
BURLINGTON	NEC 1
RESOURCES OIL S	GAS COMPANY DEC 1 4 1999 8. Well Name & Number
Address & Phone No. of Operat PO Box 4289, Farmington, NM	87499 (505) 326-9700 30-045-27711
Location of Well, Footage, Se 620'FNL, 2360'FEL, Sec.34, T-	Basin Fruitland Co. 10. Field and Pool Basin Fruitland Co. 11. County and State San Juan Co, NM
QUECK ADDRODDIATE BOX TO TH	DICATE NATURE OF NOTICE, REPORT, OTHER DATA
Type of Submission	Type of Action
Notice of Intent	Abandonment Change of Plans Recompletion New Construction
X Subsequent Report	
X Subsequent Report	Casing Repair Water Shut off
X Subsequent Report Final Abandonment	
	Casing Repair Water Shut off Altering Casing Conversion to Injection X_ Other -
Final Abandonment Tinal Abandonment 11-18-99 MIRU. ND WH. NU 11-19/24-99 TIH w/6 ½" bit. 11-26-99 TOOH w/bit. TIH top @ 2798'. interval. TOO 11-27-99 Mill perf plugs 2-3/8" 4.7# J	Casing Repair Water Shut off Altering Casing Conversion to InjectionX Other - leted Operations BOP. TOOH w/3 ½" tbg. SDON. Circ & CO to TD @ 3109'. SDON. [w/7 jts 5 ½" 15.5# K-55 LT&C csg, set @ 3108'. Lnr Lnr pre-perf @ 2931-76', & 3020-3106' across coal OH. TIH w/perf mill. SDON. BOW 2931-76', & 3020-3106'. TOOH w/mill. TIH w/97 jts BOW SECOND SECON
Final Abandonment 3. Describe Proposed or Comp. 11-18-99 MIRU. ND WH. NU 11-19/24-99 TIH w/6 ½" bit. 11-26-99 TOOH w/bit. TIH top @ 2798'. interval. TOO 11-27-99 Mill perf plugs 2-3/8" 4.7# J PT & pump act	Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - leted Operations BOP. TOOH w/3 %" tbg. SDON. Circ & CO to TD @ 3109'. SDON. (w/7 jts 5 %" 15.5# K-55 LT&C csg, set @ 3108'. Lnr Lnr pre-perf @ 2931-76', & 3020-3106' across coal OH. TIH w/perf mill. SDON. (@ 2931-76', & 3020-3106'. TOOH w/mill. TIH w/97 jts (J-55 tbg, set @ 3104'. ND BOP. NU WH. TIH w/pump & rods. Lion, OK. RD. Rig released.
Final Abandonment 3. Describe Proposed or Comp. 11-18-99 MIRU. ND WH. NU 11-19/24-99 TIH w/6 ½" bit. 11-26-99 TOOH w/bit. TIH top @ 2798'. interval. TOO 11-27-99 Mill perf plugs 2-3/8" 4.7# J PT & pump act	Casing Repair Water Shut off Altering Casing Conversion to Injection X_ Other - leted Operations BOP. TOOH w/3 %" tbg. SDON. Circ & CO to TD @ 3109'. SDON. (w/7 jts 5 %" 15.5# K-55 LT&C csg, set @ 3108'. Lnr Lnr pre-perf @ 2931-76', & 3020-3106' across coal OH. TIH w/perf mill. SDON. (a) 2931-76', & 3020-3106'. TOOH w/mill. TIH w/97 jts (a) 2931-76', & 3020-3106'. ND BOP. NU WH. TIH w/pump & rods. (b) 3104'. ND BOP. NU WH. TIH w/pump & rods. (c) 4 foregoing is true and correct. Title Regulatory Administrator Date 12/3/99 TLW
Final Abandonment 3. Describe Proposed or Comp. 11-18-99 MIRU. ND WH. NU 11-19/24-99 TIH w/6 ½" bit. 11-26-99 TOOH w/bit. TIH top @ 2798'. interval. TOO 11-27-99 Mill perf plugs 2-3/8" 4.7# J PT & pump act	Casing Repair Water Shut off Altering Casing Conversion to Injection X_ Other - leted Operations BOP. TOOH w/3 %" tbg. SDON. Circ & CO to TD @ 3109'. SDON. (w/7 jts 5 %" 15.5# K-55 LT&C csg, set @ 3108'. Lnr Lnr pre-perf @ 2931-76', & 3020-3106' across coal OH. TIH w/perf mill. SDON. (a) 2931-76', & 3020-3106'. TOOH w/mill. TIH w/97 jts (a) 2931-76', & 3020-3106'. ND BOP. NU WH. TIH w/pump & rods. (b) 3104'. ND BOP. NU WH. TIH w/pump & rods. (c) 4 foregoing is true and correct. Title Regulatory Administrator Date 12/3/99 TLW

Sm-