

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

GARY E. JOHNSON Governor

Jennifer A. Salisbury Cabinet Secretary

March 2, 1999

Ms Peggy Bradfield Burlington Res O&G Co PO Box 4289 Farmington NM 87499-4289

Re: Quinn #339, L-20-31N-08W, API 30-045-28094

Dear Ms Bradfield:

Your application to directionally sidetrack the referenced well to a new bottom hole location of 835' FSL, 1825' FWL is hereby approved. If after the well is sidetracked, the bottom hole location is closer than 790' to the drill tract boundary, this approval will be of no effect.

If you have any questions please contact me.

Yours truly,

Ernie Busel

Ernie Busch

District Geologist/Deputy O&G Inspector

EB/mk

Xc: Farmington BLM-Duane Spencer

NMOCD(Santa Fe)-Michael Stogner

C 100 337, 11

BURLINGTON RESOURCES

SAN JUAN DIVISION

February 18, 1999

Mr. Frank Chavez New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

Re:

Quinn #339

Basin Fruitland Coal 30-045-28094

1825'FSL, 835'FWL, Section 20, T-31-N, R-8-W

SF-078511

Dear Mr. Chavez:

This letter serves as an application to directionally sidetrack the referenced well. Attached is an intent sundry notice approved from the Bureau of Land Management, with the procedure for setting the whipstock and directionally drilling. Also attached is a plat showing the angle and horizontal plan. The new bottom hole location is anticipated to be 835'FSL, 1825'FWL and remain within the standard window for this Fruitland Coal well.

If you have any questions, please let me know.

Sincerely,

Peggy Bradfield

Regulatory/Compliance Administrator

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

記録 むいたんだい	UNITED STATES DEPARTMENT OF THE INTERIOR	~.	2.0		
	BUREAU OF LAND MANAGEMENT	11.	$\{S_{ij}^{E}\}_{i=1}^{N}$		
Sundry Notices and Reports on Wells 19 19727 Pure					
			- 111	2: 29	
		OF Print	5.	Lease Number SF-078511	
1. Type of Well GAS		" W 14	6. V	if∫Indian, All. o	
2. Name of Operat			7.	Unit Agreement N	
2. Name of Operat	.01				
RESOUR	CES OIL & GAS COMPANY				
	OIL & GAS COMPANY		8.	Well Name & Numb	
3. Address & Phon	ne No. of Operator		٠.	Quinn #339	
PO Box 4289,	Farmington, NM 87499 (505) 326-	9700	9.	API Well No.	
				30-045-28094	
	ell, Footage, Sec., T, R, M FWL, Sec.20, T-31-N, R-8-W, NMPM		10.	Field and Pool Basin Fruitland	
T072, L9P 832, L	MI, SEC.20, 1-31-N, K-6-W, NMPM		11.	County and State	
				San Juan Co, NM	
Final	Abandonment Altering Cas Other -	sing Convers	sion to	o Injection	
13. Describe Pr	roposed or Completed Operations		 	<u></u>	
	nded to workover the subject well	in the following	ing mai	nner:	
	the tubing. Cement open hole and			_	
	<u>-</u>		1117 AW	o, and bimb soosx	
class	B cement. Set a cement retainer		_		
class of ce	B Cement. Set a cement retainer ement below the retainer. Run and	d set a whipstoo	k and	sidetract out of	
class of ce the 7 6 deg	s B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per att	d set a whipstod c. Drill out at cached direction	ek and 480'. nal pla	sidetract out of Build angle at an. Hold angle of	
class of ce the 7 6 deg 28 de	s B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per att egrees and drill(8.4-9.0 pps LSNI	d set a whipstoom. Drill out at cached direction mud with visco	k and 480'. hal plansity	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.)	
class of ce the 7 6 deg 28 de 6 %"	s B cement. Set a cement retainer ement below the retainer. Run and "just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru	d set a whipstoom. Drill out at tached direction mud with viscon 4 ½" 10.5# J-	ck and 480'. nal place of the control of the contro	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casi:	
class of ce the 7 6 deg 28 de 6 %" with	s B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per att egrees and drill(8.4-9.0 pps LSNI	d set a whipstod c. Drill out at tached direction mud with visco un 4 %" 10.5# J- gilsonite, % pp	ek and 480'. nal place of the control of the contro	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casingele, 0.4% Halad-	
class of ce the 7 6 deg 28 de 6 %" with and 0	s B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 de original TD of 3352" TVD (3692)	d set a whipstod c. Drill out at tached direction o mud with viscon on 4 %" 10.5# J- gilsonite, % pp of excess in ope o'M.D.). Cavitat	ek and 480'. hal placesity of 55 cases flower holder the	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casing cele, 0.4% Halade). Drill a 3-7/8 Fruitland Coal	
class of ce the 7 6 deg 28 de 6 %" with and 0	B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 de original TD of 3352" TVD (3692 ation utilizing natural and air a	d set a whipstod c. Drill out at cached direction o mud with visco on 4 %" 10.5# J- gilsonite, % pp of excess in ope of M.D.). Cavitat assisted surges	ek and 480'. nal pla esity of 55 cas es floo en hole the until	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casinglele, 0.4% Halade). Drill a 3-7/8 Fruitland Coal the well stabili	
class of ce the 7 6 deg 28 de 6 %" with and 0 to th CONS OF APPACIES	s B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 ce original TD of 3352" TVD (3692 ation utilizing natural and air and the well to TD and run a 3 %"	d set a whipstod c. Drill out at cached direction o mud with viscon on 4 ½" 10.5# J- gilsonite, ½ pp 0% excess in ope 2'M.D.). Cavitate assisted surges 9.3# J-55 FJ lin	ek and 480'. hal places floor hold be the until her. T	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casing cele, 0.4% Halade). Drill a 3-7/8 Fruitland Coal the well stabilihe liner will be	
class of ce the 7 6 dec 28 de 6 %" with and 0 to th NONG OF ARCONTO	B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 de original TD of 3352" TVD (3692 ation utilizing natural and air a	d set a whipstod c. Drill out at cached direction o mud with visco un 4 %" 10.5# J- gilsonite, % pp 0% excess in ope 2'M.D.). Cavitat assisted surges 9.3# J-55 FJ lin intervals. Run	ek and 480'. hal places floor hold be the until her. T	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casing cele, 0.4% Halade). Drill a 3-7/8 Fruitland Coal the well stabilihe liner will be	
class of ce the 7 6 deg 28 de 6 %" with and 0 to th formations of ATTACHED FOR Clear pre-I	ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 at on utilizing natural and air and the well to TD and run a 3 ½" sperforated 4 SPF across the coal well will then be returned to pro-	d set a whipstod of Drill out at cached direction of mud with viscon 4 %" 10.5# Jegilsonite, % ppo excess in ope 2'M.D.). Cavitate assisted surges 9.3# J-55 FJ limintervals. Runoduction.	ek and 480'. hal pla 55 cas os flos en hole te the until her. Ti	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casing cele, 0.4% Halade). Drill a 3-7/8 Fruitland Coal the well stabilihe liner will be	
class of ce the 7 6 deg 28 de 6 %" with and 0 to th formations of ATTACHED FOR Clear pre-I	s B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 me original TD of 3352" TVD (3692 ation utilizing natural and air and the well to TD and run a 3 ½" sperforated 4 SPF across the coal	d set a whipstod of Drill out at cached direction of mud with viscon 4 %" 10.5# Jegilsonite, % ppo excess in ope 2'M.D.). Cavitate assisted surges 9.3# J-55 FJ limintervals. Runoduction.	ek and 480'. hal pla 55 cas os flos en hole te the until her. Ti	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casing cele, 0.4% Halade). Drill a 3-7/8 Fruitland Coal the well stabili he liner will be roduction tubing.	
class of ce the 7 6 deg 28 de 6 %" with and 0 to th formations of ATTACHED FOR Clear pre-I	B cement. Set a cement retainer ement below the retainer. Run and 7" just above the cement retainer grees/100' to 28 degrees, per attegrees and drill(8.4-9.0 pps LSNI hole to 3129' TVD(3439'M.D.). Ru 390sks 50/50 B-Pozmix with 3pps 0.2% CFR-3(530 cu.ft. includes 50 at on utilizing natural and air at the well to TD and run a 3 %" 9 perforated 4 SPF across the coal well will then be returned to propertify that the foregoing is true.	d set a whipstod of Drill out at cached direction of mud with viscon 4 %" 10.5# Jegilsonite, % ppo excess in ope 2'M.D.). Cavitate assisted surges 9.3# J-55 FJ limintervals. Runoduction.	ek and 480'. hal pla esity 55 cas es floe en hole te the until her. Ti the p	sidetract out of Build angle at an. Hold angle of of 30-60 seq/qt.) sing. Cement casis cele, 0.4% Halad- e). Drill a 3-7/8 Fruitland Coal the well stabili he liner will be roduction tubing. nued on back	

BOP and tests:

Surface to TD - 11" 2000 psi (minimum double gate BOP stack (Reference Figure #1 and #2). Prior to drilling out surface casing, test rams to 600 psi/30 min.

Completion - 6" 2000 psi (minimum) double gate BOP stack (Reference Figure #2). Prior to completion operations, test rams and casing to 2000 psi/15 min.

From surface to TD - choke manifold (Reference Figure #3).

Pipe rams will be actuated to least once each day and blind rams actuated once each trip to test proper functioning. An upper kelly cock valve with handle and drill string safety valves to fit each drill string will be maintained and available on the rig floor.

