

F

30-045-28211

09-04-90

F. Loc. 1060/N; 1200/E Elev. 6519 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx \_\_\_\_\_ Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx \_\_\_\_\_ Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx \_\_\_\_\_ I. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

T Gas  
R  
A  
N  
S

BO/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

TOPS	NIID	Well Log	TEST DATA						
Ojo Alamo	C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	C-104	Electric Log							
Fruitland		C-122							
Pictured Cliffs	Ditr	Dfa							
Chacra	Datr	Dac							
Cliff House	E/315.08 Acres								
Menelee									
Point Lookout									
Mancos									
Gallup									
Greenhorn									
Dakota									
Entrada									

P  
o  
o

BasinFrCoal Co. SJ S 19 T 31N R09W U A Oper. Amoco Production Co. Les. Barrett A

No. 14

Barrett A #14

A-19-31N-09W

AMOCO PRODUCTION CO.



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Farmington Resource Area  
1235 Laplata Highway  
Farmington, New Mexico 87401

TAKE  
PRIDE IN  
AMERICA

IN REPLY REFER TO:

SF-078336-B et al. (WC)  
3162.3-1 (019)

Amoco Production Company  
P.O. Box 800  
Denver, CO 80201

OCT. 18 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 14 Barrett A, sec. 19, T. 31 N., R. 9 W., San Juan County, NM,  
lease SF-078336-B.
- ✓ 2. 64 Mudge B, sec. 20, T. 31 N., R. 11 W., San Juan County, NM,  
lease SF-078096.
- ✓ 3. 62 Mudge B, sec. 21, T. 31 N., R. 11 W., San Juan County, NM,  
lease SF-078096.
- ✓ 4. 1 Florance Gas Com H, sec. 30, T. 30 N., R. 9 W., San Juan County, NM,  
lease SF-077833.
- ✓ 5. 11 Heaton A, sec. 28, T. 31 N., R. 11 W., San Juan County, NM,  
lease SF-078097.

As discussed with Cindy Burton of your company on, October 9, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller  
Chief, Branch of Mineral Resources

Enclosures

CC:  
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

**ABANDONED LOCATION**

**RECEIVED**

OCT 21 1991

OIL CON. DIV.  
DIST 3