## UNITED STATES

## DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	4 - 1 - 2 - 2	<del>11 7:51 -</del>		
		834 <b>(* 5</b> 37	5	Lease Number SF-078508
Type of Well		- 1 1 A	6.	If Indian, All. or
GAS		and Speakl		Tribe Name
			7.	Unit Agreement Name
Name of Operator				
MERIDIAN OIL				_
		<del></del>	8.	Well Name & Number
ddress & Phone No. of Operator		_	0	Nordhaus #715
PO Box 4289, Farmington, NM 87499	9 (505) 326-970	0	9.	<b>API Well No.</b> 30-045-28314
ocation of Well, Footage, Sec., T,	R, M	<del></del>	10.	Field and Pool
885'FSL, 1130'FWL, Sec.12, T-31-N,				Basin Fruitland Co
			11.	County and State San Juan Co, NM
	NAMEDE OF NOME	CE DEDODT	OTHER	DATA
CHECK APPROPRIATE BOX TO INDICATE	Type of	ee, Refort, Action	() III.DI(	<b>D</b>
<pre>'ype of Submission     X Notice of IntentA</pre>	\handonment	Change	of Pla	ans
F	Recompletion	New Co	nstruct	cion
Subsequent Report F	Plugging Back	New Co	utine 1	Fracturing
	Plugging Back Casing Repair	Water	Shut o	Ef
	Altering Casing		sion to	o Injection
_x C	Other - Recavit	ate		
Describe Proposed or Completed C	Operations			
_		bject well	in the	following manner:
It is intended to perform a work	kover on the su			
_	kover on the su	cubing. Sur	ge with	gas until formation
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation turn well to produc
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation turn well to produc
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation turn well to produc
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation turn well to produc
It is intended to perform a work	kover on the su	cubing. Sur	ge with	gas until formation turn well to produc
It is intended to perform a work	kover on the su er and 2 3/8" t 1/2" liner and	2 3/8" tub	ge with	gas until formation turn well to produc
It is intended to perform a work  Pull existing 5 1/2" lin stabilizes. Rerun the 5	kover on the su er and 2 3/8" t 1/2" liner and	2 3/8" tub	ge with	gas until formation turn well to produc
It is intended to perform a work  Pull existing 5 1/2" lin stabilizes. Rerun the 5	kover on the sum of th	2 3/8" tub	ge with	gas until formation turn well to produc