

F

30-045-28345

10-25-90

F. Loc. 955/N:1600/W

Elev. 5932 GL Spd.

Comp.

TD

PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T @ T Gas
Csg. Perf. Prod. Stim.

TRANS

BO/D Grav. 1st Del. Gas
I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

| TOPS | | NiTD | Well Log | TEST DATA | | | | | | |
|-----------------|--|---------------------|--------------|-----------|----|---|----|----|---|---------|
| Ojo Alamo | | C-103 | Plat X | Schd. | PC | Q | PW | PD | D | Ref.No. |
| Kirtland | | C-104 | Electric Log | | | | | | | |
| Fruitland | | | C-122 | | | | | | | |
| Pictured Cliffs | | Ditr | Dfo | | | | | | | |
| Chacra | | Datr | Dac | | | | | | | |
| Cliff House | | SWD-403 Acres NA | | | | | | | | |
| Menefee | | | | | | | | | | |
| Point Lookout | | | | | | | | | | |
| Mancos | | | | | | | | | | |
| Gallup | | | | | | | | | | |
| Greenhorn | | | | | | | | | | |
| Dakota | | | | | | | | | | |
| Entrada | | | | | | | | | | |

P
o
o

Unles. Entrada Co. SJ S 11 T 30N R 09W UC Oper. Amoco Production Co. Lse. Florance SWD No. 2

FLORANCE SWD #2

C-11-30N-09W

AMOCO PRODUCTION CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO:
SF-078336 (WC)
3162.3-1.0 (019)

NOV. 20 1991

RECEIVED
NOV 21 1991
OIL CON. DIV
DIST. 3

Amoco Production Company
PO Box 800
Denver, Colorado 80201

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 2 Florance SWD, NE/4NW/4 Sec. 11, T. 30 N., R. 9 W., San Juan County, New Mexico, lease SF-078336. As discussed with Cindy Burton of your company on November 6, 1991, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

1 Enclosure

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION