

F

30-045-27756

04-24-90

F. loc. 1410/N; 1610/E Elev. 6191 GL Spd. Comp. TD PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @
 Csg. Perf. Prod. Stim. T Gas

BO/D Grav. 1st Del. Gas
 MCF/D After Hrs. SICIP PSI After Days GOR 1st Del. Oil

TOPS		NiTD	X	Well Log	TEST DATA							
Ojo Alamo		C - 103		Plat	X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C - 104		Electric Log								
Fruitland				C - 122								
Pictured Cliffs		Ditr		Dfa								
Chacra		Datr		Dac								
Cliff House												
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrado												
				Acres E/320								

P
o
o
i

BasinFrCoal Co. SJ S 18 T 30N R 09W U G Oper. Amoco Production Co. Lss. Florance Gas Com I No. 3

Florance Gas Com I #3

G-18-30N-09W

AMOCO PRODUCTION CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LAPLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO:

SF-080243 et. al. (NC)
3162.3-1.0 (019)

JUL 18 1991

Amoco Production Company
PO Box 800
Denver, Colorado 80201

RECEIVED

JUL 19 1991

**OIL CON. DIV.,
DIST. 3**

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos.:

1. No. 3 Florance Gas Com I, sec. 18, T 30 N, R 9 W, SF-080243
2. No. 3 Florance "AA", sec. 8, T 30 N, R 9 W, SF-078129-A
3. No. 3 Florance "AE", sec. 25, T 30 N, R 10 W, SF-080776
4. No. 7 Florance "AD", sec. 24, T 30 N, R 10 W, SF-078116
5. No. 9 Riddle "H", sec. 17, T 30 N, R 9 W, SF-080244
6. No. 5 Elmer E. Elliott "A", sec. 15, T 30 N, R 9 W, SF-078139
7. No. 3 Giomi Gas Com "C", sec. 28, T 30 N, R 9 W, SF-078042
8. No. 1 Walker Gas Com A, sec. 31, T 31 N, R 9 W, SF-078316-F
9. No. 1 Riddle Gas Com C, sec. 30, T 31 N, R 9 W, SF-078319-A

All of the above referenced wells are located in San Juan County, New Mexico. As Discussed with Cindy Burton of your company on June 27, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

9 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION