UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

	Sundry Notices	and Reports on	Wells "-	6 712:	59
			(7)	5	Lease Number
. Type of Well		L.			If Indian, All. or Tribe Name
		- 100 Miles (100 Miles	- 256 - 1111- 2666	7.	
. Name of Operat			ion Will be the		San Juan 32-9 Unit
BURLIN RESOUR	RCES OIL & GA	S COMPANY	e de la companya de La companya de la co		
adding a pho-	V- of O-ometon	<u> </u>		8.	Well Name & Number San Juan 32-9 U#18
	ne No. of Operator Farmington, NM 874	199 (505) 326-9	700	9.	API Well No. 30-045-28942
. Location of W	ell, Footage, Sec.,	T, R, M		10.	Field and Pool
	0`FWL, Sec.17, T-31-		1	11.	Blanco Mesaverde County and State San Juan Co, NM
2. CHECK APPROPI	RIATE BOX TO INDICAT			RT, OTHER	DATA
Type of Submis			of Action	5	
Notice		_ Abandonment _ Recompletion		nge of Pl Construc	
X Subsec	quent Report	Plugging Back	Non	-Routine	Fracturing
		Carina Damaia			
_, _	- ·	_ casing Repair	Wat	er Shut o	ff
Final	Abandonment	Altering Casi	ing Con	er Shut o version t	ff o Injection
	Abandonment X	Altering Cast Other - Tubin	ing Con	er Shut o	ff o Injection
	Abandonment	Altering Cast Other - Tubin	ing Con	er Shut o	ff o Injection
	Abandonment _X_ roposed or Completed	Altering Cast Other - Tubin	ing Con	er Shut o	ff o Injection
3. Describe P: 5-29-00 M	Abandonment _X roposed or Completed IRU. SDON. OOH w/pump & rods. N TIH & freepoint th	Altering Casi Other - Tubin Operations ND WH. NU BOP.	ing Con ng repair Attempt to	version t	o Injection .bg. Tbg stuck.
5-29-00 M 5-31-00 To	Abandonment _X roposed or Completed IRU. SDON. OOH w/pump & rods. N TIH & freepoint th tbg. SDON. IH & catch fish. Pul	Altering Cast Other - Tubing Operations ND WH. NU BOP. Dog. TOOH. TIH,	ing Con ng repair Attempt to chemical c	version to TOOH w/tout tbg @	o Injection bg. Tbg stuck. 5933'. TOOH w/
5-29-00 M 5-31-00 T	Abandonment X roposed or Completed IRU. SDON. OOH w/pump & rods. M TIH & freepoint th tbg. SDON.	Altering Cast Other - Tubing Other - Tubing Other - Tubing Other O	ing Coning repair Attempt to chemical controls	version to TOOH w/to with the west to the west the west to the wes	o Injection .bg. Tbg stuck. 5933'. TOOH w/ oit, tag up @ 5970'.
5-29-00 M 5-31-00 T	Abandonment _X roposed or Completed IRU. SDON. OOH w/pump & rods. N TIH & freepoint th tbg. SDON. IH & catch fish. Pul Blow well clean.	Altering Casi Other - Tubin Operations ND WH. NU BOP. Og. TOOH. TIH, Il fish free. SDON. Og'. TOOH w/bit	Attempt to chemical c	TOOH w/tout tbg @ TIH w/b	o Injection bg. Tbg stuck. 5933'. TOOH w/ pit, tag up @ 5970'.
.3. Describe P: 5-29-00 M: 5-31-00 T:	Abandonment X roposed or Completed IRU. SDON. OOH w/pump & rods. M TIH & freepoint th tbg. SDON. IH & catch fish. Pul Blow well clean. S low well & CO to 605 set @ 6053'. ND BO	Altering Casi Other - Tubin Operations ND WH. NU BOP. Og. TOOH. TIH, Il fish free. SDON. Og'. TOOH w/bit	Attempt to chemical c	TOOH w/tout tbg @ TIH w/b	o Injection bg. Tbg stuck. 5933'. TOOH w/ pit, tag up @ 5970'.
5-29-00 M 5-31-00 T	Abandonment X roposed or Completed IRU. SDON. OOH w/pump & rods. M TIH & freepoint th tbg. SDON. IH & catch fish. Pul Blow well clean. S low well & CO to 605 set @ 6053'. ND BO	Altering Casi Other - Tubin Operations ND WH. NU BOP. Og. TOOH. TIH, Il fish free. SDON. Og'. TOOH w/bit	Attempt to chemical c	TOOH w/tout tbg @ TIH w/b	o Injection bg. Tbg stuck. 5933'. TOOH w/ pit, tag up @ 5970'.
5-29-00 M 5-31-00 T 6-1-00 T 6-2-00 B	Abandonment X roposed or Completed IRU. SDON. OOH w/pump & rods. M TIH & freepoint th tbg. SDON. IH & catch fish. Pul Blow well clean. S low well & CO to 605 set @ 6053'. ND BO	Altering Casi Other - Tubin Other - Tubin Operations ND WH. NU BOP. Og. TOOH. TIH, Il fish free. Too	ing Conng repair Attempt to chemical control with the control of the control	TOOH w/tout tbg @ TIH w/b Tods. PT &	o Injection bg. Tbg stuck. 5933'. TOOH w/ pit, tag up @ 5970'.
5-29-00 M 5-31-00 T 6-1-00 T 6-2-00 B	Abandonment X roposed or Completed IRU. SDON. OOH w/pump & rods. N TIH & freepoint th tbg. SDON. IH & catch fish. Pul Blow well clean. S low well & CO to 609 set @ 6053'. ND BO RD. Rig released.	Altering Casi Other - Tubin Other - Tubin Operations ND WH. NU BOP. Og. TOOH. TIH, Il fish free. Too	Attempt to chemical corrections. TIH w/19 w/pump & r	TOOH w/tout tbg @ TIH w/b Tods. PT &	o Injection bg. Tbg stuck. 5933'. TOOH w/ pit, tag up @ 5970'. 8/8" 4.7# J-55 tbg, 2 pump action, OK.
5-29-00 M 5-31-00 T 6-1-00 T 6-2-00 B	Abandonment X roposed or Completed IRU. SDON. OOH w/pump & rods. N TIH & freepoint th tbg. SDON. IH & catch fish. Pul Blow well clean. S low well & CO to 609 set @ 6053'. ND BO RD. Rig released.	Altering Casi Other - Tubin Operations ND WH. NU BOP. Og. TOOH. TIH, Il fish free. Toon. Op. TOOH w/bit Op. NU WH. TIH Op. NU WH. TIH Op. Title Requi	Attempt to chemical corrections. TIH w/19 w/pump & r	TOOH w/tout tbg @ TIH w/b Tods. PT &	o Injection bg. Tbg stuck. 5933'. TOOH w/ oit, tag up @ 5970'. 6/8" 4.7# J-55 tbg, c pump action, OK.

SY JMW UTTICE