UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Not	ices and Report	s on Wells	3	71	
			<u> </u>		5.	Lease Number NMSF-078505
. Type of Well GAS				·	6.	If Indian, All. or Tribe Name
					7.	Unit Agreement Name
. Name of Opera	ator			6 .5		
BURLII RESOU	VGTON RCES OIL	& GAS COMPANY				
			<u> </u>		8.	Well Name & Number
PO Box 4289	one No. of Opera , Farmington, N	ator 4 87499 (505) 3	126-9700		9 .	Seymour #3B API Well No. 30-045-30147
Tarabian of 1	Well, Footage,	Sec T. R. M			10.	Field and Pool
2305'FSL, 23	05'FEL, Sec.24,	T-31-N, R-9-W,	NMPM			Blanco MV/Basin DK County and State San Juan Co, NM
		NDICATE NATURE (F NOTICE,	REPORT,	OTHER	DATA
Type of Subm			pe of Act	ion Change	of Pla	Ing
Noti	ce of Intent	Abandonme Recomplet		New Co		
X Subs	equent Report	Plugging		_ Non-Ro	ıtine E	racturing
	-	Casing Re		_ Water		
Fina	l Abandonment	Altering _X_ Other - 1	Casing FA Dakota	_ Conver	sion to	o Injection
3. Describe	Proposed or Com	pleted Operation	ns			
2/19/02	RU W/L. Set 2-	7/8" composite p ON.	plug @ 595			plug to 3500 psi/15
2/20/02	SDON					oles, 0.23" diameter.
2/21/02	water. TIH W	/2-7/8" plug, se	et @ 5320 '	. PT plu	g to 3	, 2766 bbls slick 600 psi, OK. SDON. s, 0.23" diameter. SD
2/22/02 2/23/02	Frac Cliffhous	e/Menefee w/75.	2-3230 W/ 000# 20/40	Brady s	and, 2	205 bbls slk wtr. SDO
2/25/02	RU coil tbg un tbg. RD coil	it. TIH w/1.25"	coil tbg,	CO to 5	320'.	Blow well. TOOH w/coi
3/5-11/02	PII coil the un	it. TIH w/1.25"	coil tbg,	, CO to 5	320'.	TOOH w/coil tbg. SDON
3/12/02	TIH w/coil tbg w/mill assy	mill assy & mi & mill. SDON.	ll. Mill o	out plug	@ 5320	'. CO to 5322'. TOOH
3/13/02	TIH w/coil tbg	c. CO to 5327'.	TOOH w/coi	il tbg. S a 5275'	Stuck	shoe, pulled out. TO
3/14/02	w/wash shoe tight spot &	& coil tbg. TIH fell through.	w/mill or Tag up 0 5	n 1.25" c 5326". Mi	oil tb ll on	g, tag @ 5275'. Mill plug & pushed plug to
3/15/02	TIH w/coil tbg	w/mill & coil t & mill, tag @ Flow back well	5369'. Mi	ll through	h tigh	t spot @ 5369' to 550
3/16-17/02	Flow back well					, , , , , , , , , , , , , , , , , , , ,
3/18/02	TIH w/coil tbg mill & coil	& mill, tag @ tbg. Flow back	5503'. Mil well. SDO	N.		ed plug to 5787'. TOOF
	certify/that th	ne foregoing is	true and		.nueu c	ACCEPTED FOR RECOR
4. /I hereby					an De	
(Aga	y all	Title	Regulator	y Superv	LSOI De	
Signed MA	r Federal or Sta		Regulator		Date	APR 2 5 2002

- 3/19/02 TIH w/1.25" wash nozzle on coil tbg, tag @ 5787'. Est circ & attempt to CO. Could not get below 5787'. TOOH w/wash nozzle & coil tbg. RD. Released coil tbg unit.
- 4/3/02 RU W/L. TIH w/gauge ring, tag @ 5778'. TOOH w/gauge ring. TIH w/sand pump, CO to 5781'. SDON.
- 4/4/02 Tag up @ 5781'. Stuck bailer assy @ 5800'. Unable to work bailer free. SDON.
- 4/5/02 Work stuck bailer, unable to pull free. Drop cutting bar & cut wireline. TIH & fish cutting bar. Left bailer assy in hole. RD W/L.

Well will produce up casing as a Mesaverde only. Dakota formation is TA w/junk in hole @ 5800'.