Form 3160-5 *(December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

Expires: September 30, 1990

. 3		3.				
5	1 0000	Dagian		an 4	Camial	NI.
J.	Lease	Design	iation	anu	Seriai	INO
		7				

Do not use this form	HOTICES AND REFORT	S ON WELLS	SF 078988
Use 'A	6. If Indian, Allottee or Tribe Name		
		7.55	7. If Unit or ÇA, Agmt. Design.:
SU	BMIT IN TRIPLICATE	₩213 g 3.2.	Northeast Blanco Unit
1. Type of Well: oil well	gas well X	other	8. Well Name and No.:
2. Name of Operator: Dev	von Energy Corporation		N.E.B.U. #323
	00 N. Butler Avenue, Suite 211,	Farmington, NM 87401	9. API Well No.:
4. Location of Well: (Footage, Sec., T.,	R., M., or Survey Description)		30-045-31023
			10. Field & Pool/Exploratory Area:
1990 PAIL 1	1255 FWW - C4: 10 TY	MAL DOW	Basin Dakota/Mesaverde
1/// FNL, 1	1375' FWL - Section 19, T3	oin, kow	11. County or Parish, State:
			San Juan, New Mexico
	OPRIATE BOX(s) TO INDICATI	E NATURE OF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSION		TYPE O	F ACTION
XNotice of Inten	t	Abandonment	Change of Plans
		Recompletion	New Construction
Subsequent Rep	oort	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
Final Abandonn	nent Notice	Altering Casing	Conversion to Injection
		(Note: Report res	Verde/Dakota Commingle Sults of multiple completion on Well Completion Report and Log form.)
13. DESCRIBE PROPOSED OR COMP starting any proposed work. If well is pertinent to this work.)*	PLETED OPERATIONS (Clearly is directionally drilled, give subsu	state all pertinent details, and give irface locations and measured and i	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well in pertinent to this work.)*	is directionally drilled, give subsu	state all pertinent details, and give rface locations and measured and t	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the factorial of the factorial	is directionally drilled, give subsu following:	state all pertinent details, and give irface locations and measured and t	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the to the MIRU service unit. NDWH, NUBOP 2. TOOH with tubing.	is directionally drilled, give subsu following: PE.	state all pertinent details, and give irface locations and measured and t	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the start of the service unit. NDWH, NUBOP 2. TOOH with tubing. 3. Set CIBP at 6000' and test to 4400 psi	is directionally drilled, give subsu following: PE.	state all pertinent details, and give irface locations and measured and t	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the start of th	is directionally drilled, give subsufollowing: PE. i.	rface locations and measured and t	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the file. MIRU service unit. NDWH, NUBOP 2. TOOH with tubing. 3. Set CIBP at 6000' and test to 4400 psi is Perforate Point Lookout intervals. 5. Frac Point Lookout interval with 100,0 is Set plug at 5509'.	is directionally drilled, give subsufollowing: PE. i. 000 gal slickwater and 100,000 pe	rface locations and measured and t	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the file. MIRU service unit. NDWH, NUBOP 2. TOOH with tubing. B. Set CIBP at 6000' and test to 4400 pside. Perforate Point Lookout intervals. Frac Point Lookout interval with 100,0 Set plug at 5509'. Perforate Menefee and Cliffhouse intervals.	is directionally drilled, give subsufollowing: PE. i. 000 gal slickwater and 100,000 per	ounds sand.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the file. MIRU service unit. NDWH, NUBOP 2. TOOH with tubing. B. Set CIBP at 6000' and test to 4400 psi is Perforate Point Lookout intervals. Frac Point Lookout interval with 100,0 is Set plug at 5509'. Perforate Menefee and Cliffhouse intervals. Frac Menefee and Cliffhouse intervals.	is directionally drilled, give subsufollowing: PE. i. 000 gal slickwater and 100,000 per	ounds sand.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the factorial and the factorial and the factorial and test to 4400 psi factorial and test to	is directionally drilled, give subsufollowing: PE. i. 000 gal slickwater and 100,000 per	ounds sand.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the factorial and the fact	following: PE. i. 000 gal slickwater and 100,000 pervals. Is with 100,00 gal slickwater and	ounds sand. 100,000 pounds sand. d.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the file. MIRU service unit. NDWH, NUBOP 2. TOOH with tubing. Set CIBP at 6000' and test to 4400 psi 4. Perforate Point Lookout intervals. Frac Point Lookout interval with 100,0 Set plug at 5509'. Perforate Menefee and Cliffhouse intervals. Frac Menefee and Cliffhouse intervals. Set plug at 4700'. Perforate Lewis interval. Frac Lewis intervals with 70 quality in 12. Drill out all Mesa Verde plugs and flo	following: PE. i. 000 gal slickwater and 100,000 pervals. Is with 100,00 gal slickwater and	ounds sand. 100,000 pounds sand. d.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the file. MIRU service unit. NDWH, NUBOP 2. TOOH with tubing. Set CIBP at 6000' and test to 4400 psi 4. Perforate Point Lookout intervals. Frac Point Lookout interval with 100,0 5. Set plug at 5509'. Perforate Menefee and Cliffhouse intervals. Set plug at 4700'. Perforate Lewis interval. Frac Lewis interval. Perforate Lewis interval. Drill out all Mesa Verde plugs and file. Drill out Dakota CIBP.	following: PE. i. 000 gal slickwater and 100,000 pervals. s with 100,00 gal slickwater and N2 foam and 200,000 pounds san low well to clean up and establish	ounds sand. 100,000 pounds sand. d.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the file. MIRU service unit. NDWH, NUBOP 2. TOOH with tubing. 3. Set CIBP at 6000' and test to 4400 psi 4. Perforate Point Lookout intervals. 5. Frac Point Lookout interval with 100,0 5. Set plug at 5509'. 7. Perforate Menefee and Cliffhouse intervals. 8. Frac Menefee and Cliffhouse intervals. 9. Set plug at 4700'. 10. Perforate Lewis interval. 11. Frac Lewis intervals with 70 quality 10. Peril out all Mesa Verde plugs and file. 12. Drill out Dakota CIBP. 14. Run production tbg and connect well.	following: PE. i. 000 gal slickwater and 100,000 pervals. s with 100,00 gal slickwater and N2 foam and 200,000 pounds san low well to clean up and establish	ounds sand. 100,000 pounds sand. d. initial production rate.	pertinent dates, including estimated date of true vertical depths for all markers and zones
starting any proposed work. If well is pertinent to this work.)* Devon Energy proposes to do the start of th	following: DE. i. 000 gal slickwater and 100,000 pervals. s with 100,00 gal slickwater and N2 foam and 200,000 pounds san ow well to clean up and establish to gas sales line. hole commingled Mesa Verde-Da	ounds sand. 100,000 pounds sand. d. initial production rate.	pertinent dates, including estimated date of true vertical depths for all markers and zones

Title

Approved by Is/ Jim Lovato

Conditions of approval, if any: