

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well GAS	API # (assigned by OCD)
2. Name of Operator Meridian Oil Inc.	5. Lease Number Fee
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	6. State Oil&Gas Lease Fee
4. Location of Well, Footage, Sec., T, R, M 880'FSL, 2210'FWL Sec.33, T-31-N, R-11-W, NMPM, San Juan Co.	7. Lease Name/Unit Name Myra Cummins
	8. Well No. 1
	9. Pool Name or Wildcat Basin Dakota
	10. Elevation:

Type of Submission	Type of Action	
☒ Notice of Intent	☒ Abandonment	☐ Change of Plans
☐ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other -	

13. Describe Proposed or Completed Operations

It is intended to plug and abandon this well per the attached procedure and wellbore diagram.

RECEIVED
JUL - 8 1992
OIL CON. DIV.]
DIST. 3

SIGNATURE *John Bradfield* (PMP) Regulatory Affairs July 2, 1992

(This space for State Use)

Approved by Original Signed by CHARLES GHOLSON Title DEPUTY OIL & GAS INSPECTOR, DIST. 3 Date JUL 08 1992

MYRA CUMMINS #1 DK
UNIT N SECTION 33 T31N R11W
San Juan County, New Mexico
P & A Procedure

1. Install & test rig anchors. MI blow tank. MOL and RUSU (Bedford). Comply to all NMOC, BLM, & MOI, rules & regulations. NU 6" BOP and stripping head. Test operation of rams. Install 2-7/8" relief line.
2. TOH w/208 Jts 2-3/8" tbg. Note: Surface pressures indicate a pkr may be in hole. This well has a csg leak. Pressure test tbg to 2000#.
3. Run guage ring on sand line to 6622' (50' above top DK perf). TIH w/4-1/2" cmt ret on tested 2-3/8" tbg & set @ 6622', est rate, & sq w/34 sx cmt. This will fill DK perfs & csg w/100% excess cmt. PU & dump 5 sx cmt on top ret & reverse out. Pressure test csg to 500 psi. Circ hole w/ mud: 15# sodium bentonite w/non-fermenting polymer, 9# gal weight, & 50 qs vis or greater. TOH.
4. Perf 2 sq holes @ 5870' (50' below top of Gallup). TIH w/4-1/2" cmt ret on 2-3/8" tbg & set @ 5860'. Est rate & pump 55 sx cmt into sq perfs. (This will cover backside of csg from 5870' to 5770' (50' above top of Gallup w/100% excess cmt). Sting out of ret & dump 12 sx cmt on top ret. (This will fill csg from 5860' to 5770' w/50% excess cmt). Reverse out. TOH.
5. Perf 2 sq holes @ 3753' (50' below top of Mesaverde). TIH w/4-1/2" cmt ret on 2-3/8" tbg & set @ 3745'. Est rate & pump 55 sx cmt into sq perfs. (This will cover backside of csg from 3753' to 3653' (50' above top of Mesaverde w/100% excess cmt). Sting out of ret & dump 12 sx cmt on top ret. (This will fill csg from 3745' to 3653' w/50% excess cmt). PU & reverse out. Pressure test csg to 500#.
6. Pull up to 2307' (50' below top Pictured Cliffs) & spot 12 sx cmt. This will fill csg from 2307' to 2207' (50' above top Pictured Cliffs) w/50% excess cmt.
7. Perf 2 sq holes @ 1940' (50' below top of Fruitland). TIH w/4-1/2" cmt ret on 2-3/8" tbg & set @ 1930'. Est rate & pump 55 sx cmt into sq perfs. (This will cover backside of csg from 1940' to 1840' (50' above top of Fruitland w/100% excess cmt). Sting out of ret & dump 12 sx cmt on top ret. (This will fill csg from 1930' to 1840' w/50% excess cmt). PU & reverse out. Pressure test csg to 500#.
8. Perf 2 sq holes @ 883' (50' below top of Kirtland). TIH w/4-1/2" cmt ret on 2-3/8" tbg & set @ 870'. Est rate & pump 44 sx cmt into sq perfs. (This will cover backside of csg from 883' to 605' (50' above top of Ojo Alamo w/100% excess cmt). Sting out of ret & dump 22 sx cmt on top ret. (This will fill csg from 870' to 605'). PU & reverse out. Pressure test csg to 500#. TOH & lay down tbg.
9. Perf 2 sq holes @ 381' (50' below surface csg shoe). Est rate down 4-1/2" csg & out bradenhead valve & circ cmt (about 110 sx cmt).

MYRA CUMMINS #1 DK - P & A

10. Cut off wellhead below surface casing flange and install dry hole marker to BLM specs.
11. Restore location to BLM specs.

Approve: _____
R. F. Headrick

PMP

MYRA CUMMINS #1 DK

UNIT N SECTION 33 T31N R11W
SAN JUAN COUNTY, NEW MEXICO

