

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

3004510052

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Yager LS

8. Well No.

1

9. Pool name or Wildcat

Blanco Mesaverde

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Amoco Production Company

Attention:

Gail M. Jefferson, Rm 1295C

3. Address of Operator

P.O. Box 800

Denver

Colorado

80201

(303) 830-6157

4. Well Location

Unit Letter

M

: 990

Feet From The

South

Line and

990

Feet From The

West/

Line

Section

31

Township

31N

Range

11W

NMPM

San Juan

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company requests permission to plug and abandon the above referenced well per the attached procedures.

If you have any questions please contact Gail M. Jefferson at (303) 830-6157.

RECEIVED
AUG 22 1995
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Gail M. Jefferson

TITLE

Sr. Admin. Staff Asst.

DATE

08-21-1995

TYPE OR PRINT NAME

Gail M. Jefferson, Rm 1295C

TELEPHONE NO. (303) 830-6157

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

AUG 22 1995

CONDITIONS OF APPROVAL, IF ANY:

Notify OGD in time to witness

Yager LS #1

Orig. Comp. 3/53

TD = 4852', PBTD = open hole

Page 2 of 2

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
3. POOH with 2" tbg. RIH with tbg and CIBP. Set CIBP at 4100'. Test casing integrity to 500#. Run short string CBL to determine TOC. Pull up hole and spot 100' of cement on top of CIBP. (33 cuft cement) RIH with perf gun and shoot squeeze holes at TOC and attempt to circulate to surface. If unable to circulate ensure the following intervals are covered 100' inside and outside:

Pictured Cliffs @2280
Fruitland Coal @1922
Ojo Alamo @905
221 to surface

4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
5. Contact FMC and ship surface equipment to yard or other location per instructions.
6. Turn over to John Schwartz for reclamation.
7. Rehabilitate location according to BLM or State requirements.