1		.				1	
-1	Submit 3 Copies to Appropriate District Office	Energy, Minerals and Natural Resources Department of the Office O				Form C-103 Revised 1-1-89	
	DISTRICT I P.O. Box 1980, Hobbs, NM 88240				WELL API NO.		
	DISTRICT II P.O. Drawer DD, Artesia, NM 882				5. Indicate Type	3004510168 of Lease	
DISTRICT III IUU Rio Brazos Rd., Aztec, NM 87410			M APR	N APR 1 8 1936		STATE FEE X 6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR PORTE PER OR PER OFFICE P				N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
+	Type of Well:				Wallace Gas Com		
	OIL GAS WELL WELL	▼ other					
	2. Name of Operator Attention:			y Haefele	8. Well No.	1A	
	Address of Operator P.O. Box 800 Denver	Colorado	80201	(303) 830-4988	9. Pool name or	Wildcat Pictured Cliffs	
	4. Well Location Unit Letter C :	990 Feet From The	North	Line and 16	50 Feet From	m The West Line	
	25		2411 -	4.4387		Can then	
ŀ	Section 35 Township 31N Range 11W NMPM San Juan County						
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5695' GR							
	Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING							
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT							
PULL OR ALTER CASING CASING TEST AND CEMENT JOB							
(OTHER:			OTHER:			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.							
Amoco Production Company has plugged the Pictured Cliffs formation in this well per the following:							
MIRUSU 12/12/95. Set cement retainer at 2265'. Fill hole and circulate gas out. Pressure test casing to							
500 psi. Run CBL 250-2256'. TOC 508'. Set packer at 2231', test to 1000 psi, leaked, tubing held. Reset							
packer at 1673', test tubing to 1000 psi, held. Reset packer at 1116', test to 1000 psi, tubing held. Pressure							
up tubing 500 psi. Found casing leak at surface pipe. Shoot 2 squeeze holes at 300'. Pump 100 sx Class B							
cement from surface to 300'. Tag cement at 182'. Drill out to 314'. Pressure test casing to 500 psi, held.							
	ND BOP, NU WH. RDMOSU 12/16/95.						
Note: This wellbore is now called the Wallace Gas Com #1A (formerly the Wallace Gas Com #2). This well							
	will be deepened t	o the Mesaverde for	ormation.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
	SIGNATURE Patty H	aefele		Staff Ass	istant	DATE04-16-1996	
_	TYPE OR PRINT NAME	Patty Haefele				TELEPHONE NO. (303) 830-4988	
(This space for State Use)							
	$\cap \ell$	Rolinso	\sim	ITTLE DEPUTY OIL & GAS	INSPECTOR, DIS	ST. #3 ΛPR 1 R 199/	
	APPROVED BY			TITLE	······································	DATE ALL I U 1770	