

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-8444	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION		8. Farm or Lease Name State Gas Com "EG"	
3. Address of Operator P. O. Box 480, Farmington, New Mexico		9. Well No. 1	
4. Location of Well UNIT LETTER C 1450 FEET FROM THE West LINE AND 790 FEET FROM THE North LINE, SECTION 32 TOWNSHIP 31-N RANGE 12-W NMPM.		10. Field and Pool, or Wildcat Basin Dakota	
15. Elevation (Show whether DF, RT, GR, etc.) 5993' (DBS)		12. County San Juan	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

As a result of production declining to uneconomical rates on the subject State Gas Com "EG" No. 1, we propose to:

1. Move in workover rig.
2. Pull tubing.
3. Run east iron drillable bridge plug and set at about 6880'.
4. Re-run tubing, snub well in, and test.



Verbally approved October 22, 1965, A. R. Kendrick to F. H. Hollingsworth.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>G. W. Eaton, Jr.</u>	TITLE <u>Area Engineer</u>	DATE <u>October 22, 1965</u>
APPROVED BY <u>Emory C. Anderson</u>	TITLE <u>Sup Dist TTB</u>	DATE <u>10-25-65</u>
CONDITIONS OF APPROVAL, IF ANY:		