Form 3160-5

(June, 1990)

## **UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROP Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

14-20-603-734

JUNDIN	 	 	_
	4 4 - 4-10	 	antru to a different reservoir

Do not use this form for proposals to drill, or to deepen or reentry to a different reservoir.

Navajo

6. If Indian, Allotte or Tribe Name

Use "APPLICATION FOR PERMIT" for such proposals	Navajo
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well	Horseshoe Gallup
X Oil Well Gas Well Other	8. Well Name and No.
2. Name of Operator	Horseshoe Gallup Unit 40
Central Resources, Inc.	9. API Well No.
3. Address and Telephone No.	30-045-10389
1775 Sherman Street, Suite 2600 Denver CO 80203-4313 (303) 830-0100	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, T, R, M, or Survey Description)	Horseshoe Gallup
1980' FNL & 660' FWL Sec. 29-T31N-R16W	11. County or Parish, State
	San Juan, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER	R DATA
TYPE OF SUBMISSION TYPE OF ACTION	

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF ACTION							
THE OF COSMICCION	X Abandonment	Change of Plans						
Notice of Intent	Recompletion	New Construction						
Notice of interior	Plugging Back	Non-Routine Fracturing						
X Subsequent Report	Casing Repair	Water Shut-Off						
<u> </u>	Altering Casing	Conversion to Injection						
Final Abandonment Notice	Surface Casing/Cementing	Dispose Water						
	Other: CHANGE OF OPERATOR	(Note: Report results of multiple completion on Well						
		Completion or Recompletion Report and Log form).						

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.

If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)

- 1. MIRU cementers. Pump 30 sacks cement @ 1362'. WOC.
- 2. Tag top of cement @ 902'. Nipple up to 4 1/2" casing.
- 3. Pump 130 sacks down casing, circ. up bradenhead to surface. Circ. through casing parted @ 420'.
- 4. Cut off wellhead and casing, install cap and dry hole marker.
- 5. Restore location.

statements or representations as to any matter within its jurisdiction.

Abandonment operations were witnessed by Herman Lujan from the BLM of Farmington, NM.



WILL GOM. DIV Date: 1/16/96 Title: Superintendent/Engineer Signed: Approved by Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and waifully to make to any department or agency of the United States any false, fictitious or frauducent

\* See Instructions on Reverse Side



## 

P. O. BOX 302 • FARMINGTON, NEW	P. O. BOX 302 • FAHMINGTON, NEW MEXICO 8/499 • (505) 632-3683					
	DATE 12-22-95					
CUSTOMER: CENTER RESCUECES IN	WELL # Horseshoe Gally #40					
CEMENT USED: 100 3X.	DISPLACEMENT BARRELS: .5. 3					
CEMENT CIRCULATED:	DISPLACEMENT RATE: 2.C					
CEMENT RATE: Q. C	DISPLACEMENT PRESSURE: 160 16.					
PRESSURE: 100 16.	DISPLACEMENT TIME:					
CEMENT TIME: 20 min	PLUG BUMP TIMES & PRESSURE:					
OTHER: 1 9:09 balance plus @ 1342						
(2) 1:25 circulate cement from 420 It to snapace						
taged cement plug @ 902 It.	1					
<del></del>						