	Form 9 (April	
ſ	- 1	1
- 1		i

(A)	DLII 18	02)	
		•	

## (SUBMIT IN TRIPLICATE)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency	-iite	-owitain
Allottee		
Lease No. 1	-20-	60L-122

Sec 29				
CIMDDV 1	MOTICES AN	IN DEDADTE	ON WRECEIVE	<b>n</b>
SUNDKI	NOTICES AF	ND REPORTS	ON WELLETYE	U
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF V	VATER SHUT-OFF OCT 7 1958	
NOTICE OF INTENTION TO CHANGE PL	ANS	SUBSEQUENT REPORT OF S	HOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER	R SHUT-OFF	SUBSEQUENT REPORT OF A	LITERING CISING JEOLOGICAL JE	√EY
NOTICE OF INTENTION TO REDRILL OF	R REPAIR WELL	SUBSEQUENT REPORT OF F	REDRILLING ON HEPAIN DE SEW ME	XICO
NOTICE OF INTENTION TO SHOOT OR	ACIDIZE	SUBSEQUENT REPORT OF A	ABANDONMENT	
NOTICE OF INTENTION TO PULL OR AL	LTER CASING	SUPPLEMENTARY WELL HIS	STORYX	
NOTICE OF INTENTION TO ABANDON W	NELL			
(INDICATE	E ABOVE BY CHECK MARK NA	ATURE OF REPORT, NOTICE, OR	OTHER DATA)	
		10-6	, 19	8
Ute sountain Tribal	2_20			· <b>-</b>
Vall No 27 is less	tol 660 ft from	N line and 1020	ft. from $\stackrel{E}{\longrightarrow}$ line of sec. 29	
/eli No is loca	atedit. Ifon	The and 1930	it. from	-
(½ Sec. and Sec. No.)	31-N	1L W NA	That	
(½ Sec. and Sec. No.)	(Twp.)	(Range) (Mer	idian)	
Verde Gallup	San Juan Cou	nty	New Mexico	
(Field)	(County or	Subdivision)	(State or Territory)	
9 1	0 1 1	1 : ಕ್ಷರ <b>ು</b> . ೧		
he elevation of the derrick	moor above sea leve			
	11001 43010 004 1010	:1 18 _ <i>222</i> # 1t.		
		S OF WORK		
	DETAIL	S OF WORK	sed casings; indicate mudding jobs, cement	; <del>-</del>
State names of and expected depths to	DETAIL objective sands; show sizes ing points, and all oth	S OF WORK , weights, and lengths of proposer important proposed work)	sed casings; indicate mudding jobs, cement	
State names of and expected depths to  A 7-7/8* hole was	DETAIL objective sands; show sizes ing points, and all oth drilled to 350	S OF WORK , weights, and lengths of proposer important proposed work)  O and 5 km casins	Was camented at 35001 w	1 th
A 7-7/8" hole was 50 SX regular 1:1 Pox	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with ha gol	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx remil	was comented at 3500; was around shoe and 100 a	i th
A 7-7/8" hole was 50 sx regular thru cultistage	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with 1% gel e tool at 2381:	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r	was cemented at 3500° was around shoe and 100 s	i.th X
A 7-7/8" hole was 50 sx regular thru multistage bailing test at 3501	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with 1,5 gel e tool at 2381: r covered 12	S OF WORK  weights, and lengths of proposer important proposed work)  of and 52 <sup>n</sup> casing  and 100 ax regul  A cable tool r  WPD and 12 ROPD.	was comented at 3500° was around shoe and 100 s ig was moved on the hole A coment retainer was	i.th X
A 7-7/8" hole was 50 sx regular 1:1 Poxice bailing test at 3501 tali33 and the shoe was	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with ha gel e tool at 2381: 'r covered 12 vas rece ented v	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500' was around shoe and 100 s ig was moved on the hole A coment retainer was	ith x and set
A 7-7/8" hole was 50 sx regarm 1:1 Poxice bailing test at 3501 to 3133° and the shoe was only was drilled to 364	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented viol. After run	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500' was around shoe and 100 s ig was moved on the hole A coment retainer was	ith x and set
A 7-7/8" hole was 50 sx regular 1:1 Poxice bailing test at 3501 to 3133 and the shoe was orilled to 361	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented viol. After run	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500° was around shoe and 100 s ig was moved on the hole A coment retainer was	ith x and set
A 7-7/8" hole was 50 sx regular 1:1 Poxice bailing test at 3501 t 3133 and the shoe was old was drilled to 361	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented viol. After run	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500° was around shoe and 100 s ig was moved on the hole A coment retainer was ler. After WOC a 1-3/1° began caving and was be	ith x and set
A 7-7/8" hole was 50 sx regarm 1:1 Poxice bailing test at 3501 to 3133° and the shoe was only was drilled to 364	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented viol. After run	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500' was around shoe and 100 s ig was moved on the hole A coment retainer was	ith x and set
A 7-7/8" hole was 50 sx regard 1:1 Poxice balling test at 3501 to 361 was drilled to 361	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented viol. After run	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500° was around shoe and 100 s ig was moved on the hole A coment retainer was ler. After WOC a 1-3/1° began caving and was be	ith x and set
A 7-7/8" hole was 50 sx regarm 1:1 Poxice bailing test at 3501 to 3133° and the shoe was only was drilled to 364	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented with Alter runs	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500° was around shoe and 100 s ig was moved on the hole A coment retainer was ler. After WOC a 1-3/1° began caving and was be	ith x and set
A 7-7/8" hole was 50 sx regular 1:1 Poxice bailing test at 3501 to 3133 and the shoe was orilled to 361	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with his gel e tool at 2381: ' r covered 12 was rece ented with Alter runs	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  PPD and 1½ POPD.  th 150 sx regul	was comented at 3500° was around shoe and 100 s ig was moved on the hole A coment retainer was ler. After WOC a 1-3/1° began caving and was be	ith x and set
A 7-7/8" hole was 50 sx regard 1:1 Poxice balling test at 3501 to 3133 and the choc was drilled to 364 leaned out at he end o	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with 1% gel e tool at 2381. ' r covered 12 was rece ented with 1% after runn of the month.	S OF WORK  weights, and lengths of proposer important proposed work)  o' and 5½" casing and 100 ax regul  A cable tool r  WPD and 1½ ROPD.  of th 150 ax regulating logs the hole	was camented at 3500' was around shoe and 100 s ig was moved on the hole A coment retainer was ter. After WOC a 1-3/1" began caving and was be	ith x and set
A 7-7/8" hole was 50 sx regular 1:1 Poxition thru multistage bailing test at 3501 to 3631 and the shoe was drilled to 364 leaned out at he end of tunderstand that this plan of works	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with ha gel e tool at 2381: 'recovered 12 was rece ented v io'. After run of the month.	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  WPD and 1½ ROPD.  The third logs the hole	was camented at 3500' was around shoe and 100 s ig was moved on the hole A coment retainer was ter. After WOC a 1-3/1" began caving and was be	ith x and set
A 7-7/8" hole was 50 sx regard 1:1 Poxically thru multistage bailing test at 3501 to 361 was drilled to 361 to another than the end of the end	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with 1% gel e tool at 2381. ' r covered 12 was rece ented with 1% after runn of the month.	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  WPD and 1½ ROPD.  The third logs the hole	was camented at 3500' was around shoe and 100 s ig was moved on the hole A coment retainer was ter. After WOC a 1-3/1" began caving and was be	ith x and set
A 7-7/8" hole was 150 sx regard 1:1 Poxically thru multistage bailing test at 3501 t 31:33 and the shoe was columns drilled to 361 leaned cut at he end of  Tunderstand that this plan of works Company Standard Company	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with ha gel e tool at 2381: 'recovered 12 was rece ented v io'. After run of the month.	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  WPD and 1½ ROPD.  The third logs the hole	was camented at 3500' was raround shoe and 100 s ig was moved on the hole A coment rotainer was began caving and was be  OCTO 1958  y before operations may be commonded.	ith x and set
A 7-7/8" hole was 50 sx regards 1:1 Poxice bailing test at 3501 t 3133' and the shoe was crilled to 361 leaned cut at he end of tunderstand that this plan of works standard (Chandard Co.	DETAIL objective sands; show sizes ing points, and all oth drilled to 350 mix with ha gel e tool at 2381: 'recovered 12 was rece ented v io'. After run of the month.	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  WPD and 1½ ROPD.  The third logs the hole	was camented at 3500' was raround shoe and 100 s ig was moved on the hole A coment rotainer was began caving and was be  OCTO 1958  y before operations may be commonded.	ith x and set
A 7-7/8" hole was 50 sx regard 1:1 Poxice balling test at 3501 t 31:33' and the shoe was drilled to 361 leaned cut at he end of standard 0 Address Box 1581.	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with 1% gel e tool at 2381. ' r covered 12 was rece ented with 1 after run of the month.  must receive approval in well Company of T	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  WPD and 1½ ROPD.  The third logs the hole	was camented at 3500' was raround shoe and 100 s ig was moved on the hole A coment rotainer was began caving and was be  OCTO 1958  y before operations may be commonded.	ith x and set
A 7-7/8" hole was 50 sx regard 1:1 Poxitions 1:1 Poxitions that at 3501 to 31:33' and the shoe was drilled to 361	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with 1% gel e tool at 2381. ' r covered 12 was rece ented with 1 after run of the month.  must receive approval in well Company of T	S OF WORK  weights, and lengths of proposer important proposed work)  and 5½ casing and 100 sx regul  A cable tool r  WPD and 1½ ROPD.  The third logs the hole	was camented at 3500' was raround shoe and 100 s ig was moved on the hole A coment rotainer was began caving and was be  OCTO 1958  y before operations may be commonded.	ith x and set
A 7-7/8" hole was 50 sx regard 1:1 Poxitions 1:1 Poxitions that at 3501 to 31:33' and the shoe was drilled to 361	DETAIL objective sands; show sizes ing points, and all off drilled to 350 mix with 1% gel e tool at 2381. ' r covered 12 was rece ented with 1 after run of the month.  must receive approval in well Company of T	S OF WORK  weights, and lengths of proposer important proposed work)  of and 5½ casing and 100 ax regul  A cable tool r  well and 1½ popple  th 150 ax regul  ing logs the hole  writing by the Geological Surve	was camented at 3500' was raround shoe and 100 s ig was moved on the hole A coment rotainer was began caving and was be  OCTO 1958  y before operations may be commonded.	ith x and set

U. S. GOVERNMENT PRINTING OFFICE 16-8437b-8