

5 BLM, Durango
UNIT STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other Instructions
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

14-20-604-1951

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo CCC

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Horseshoe

9. WELL NO.

280

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 27, T31N, R16W, NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

990' FNL - 990' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5530' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request permission to plug & abandon the subject well as follows:

1. Pull 52 joints 2-3/8" OD, 4.7#, 8 Rd, EUE tubing and tear down wellhead equipment.
2. Set 221' plug across the Gallup formation from P.B.T.D. 1656 to 1435' (50' above top perf.) using 25 sx class "B" cement (30 cf).
3. Set 100' plug at surface.
4. Install dry hole monument.
5. Clean well location of all equipment, pipe, junk and trash.
6. Will complete surface restoration.
7. Will cut and remove tie-downs.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan
Sherman E. Dugan

TITLE

Geologist

DATE 4-30-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: