

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved:  
Budget Bureau No. 1004-  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

14-20-603-734

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup Unit

9. WELL NO.

26

10. FIELD AND POOL OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 29-31N-10W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ X-Water Injection

2. NAME OF OPERATOR  
ARCO Oil and Gas Company

3. ADDRESS OF OPERATOR  
P. O. Box 1610, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface Unit "B"

14. PERMIT NO. No API No. Assigned

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
5488' GR

660' FNL & 1980' FEL, Sec. 29

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

RECEIVED  
NOV 19 1986

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was shut in during June 1972, because of a low injection rate.

This well is in a large unit which is now under waterflood operations. Waterflood and tertiary recovery studies are currently being conducted. These studies may result in a revised waterflood, plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

Therefore we would like to cancel our approved plans for P&A and request extended shut-in status.

RECEIVED  
NOV 21 1986  
OIL CON. DIV.  
DIST. 9

18. I hereby certify that the foregoing is true and correct

915-688-5672

SIGNED Ken W. Hosnell

TITLE Engr. Tech. Spec.

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED  
DATE 11-12-86

INCH

John D. Keller

FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

NMOCC