

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
 State Fee **X**
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator El Paso Natural Gas Company	7. Unit Agreement Name
3. Address of Operator Box 990, Farmington, New Mexico	8. Farm or Lease Name Lawson Pool Unit
4. Location of Well UNIT LETTER H 1650 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 31N RANGE 11W NMPM.	9. Well No. 1
	10. Field and Pool, or Wildcat Blanco Mesa Verde

15. Elevation (Show whether DF, RT, GR, etc.) 5857' GL	12. County San Juan
--	-------------------------------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER Case, cement, fracture treat M. V. <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER _____ <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To increase production it is intended to workover and recomplete this well in the following manner:

Squeeze cement the 7" annulus at top of Fruitland (2140').

Clean out the old hole or whipstock and redrill through the Mesa Verde formation to approximately 4930'.

Run full string of 4 1/2" production casing and run cement to tie into the bottom of the 7" casing.

Perforate and sand-water frac the Mesa Verde formation.

In the event it is necessary to whipstock, squeeze cement the open hole through a retainer set near the bottom of the 7" casing with approximately 250 sacks of cement.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original signed by
 Carl E. Matthews TITLE Petroleum Engineer DATE _____

APPROVED BY [Signature] TITLE Supervisor Dist. # 3 DATE 6-1-65

CONDITIONS OF APPROVAL, IF ANY: