

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1000-1115
Expires September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.
SF 080517

6. If Indian, Allottee or Tribe Name

7. If Unit or C.A. Agreement Designation

8. Well Name and No.
Holmberg Gas Com #1

9. API Well No.
30-045-11281

10. Field and Pool, or Exploratory Area
Blanco Mesaverde

11. County or Parish, State
San Juan, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Amoco Production Company Attn: John Hampton

3. Address and Telephone No.

P.O. Box 800, Denver, Colorado 80201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

B 890' FNL x 1650' FEL, Sec. 28-32N-10W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or
Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Amoco Production Company plugged and abandoned the subject well as follows:

1. Set cmt retainer @ 4300'. Sq perfs @ 4730'-4802' and 5145'-5254' with 75 sx Class B neat cmt.
2. Sting out of ret with 2 BBL cmt in tbq. Pull up to 4245'. Pmp 52 BBL 9 ppg mud from 4250' to 2950'.
3. Pmu 75 sx Class B neat cmt.
4. Tag cmt @ 2559'. Perf 2500' with 4 JSPF.
5. Set cmt ret @ 2433'. Pmp 170 sx Class B neat cmt.
6. Top of cmt @ 2200'. Perf @ 1700' with 4 JSPF.
7. Set cmt ret @ 1651'. Pmp 400 sx Class B neat cmt.
8. Top of cmt @ 1475'. Pmp 78 sx Class B neat cmt.
9. Tag cmt @ 1015'. Cut 7" csg @ 879'. Unable to pull 7" csg.
10. Sq holes in 7" csg with 500 sx Class B neat cmt. Circ to surface thru Braden Head with 10 BBL cmt. Sq 2 BBL cmt into formation.
11. Spot 65 sx cmt plug inside 7" csg 636'-336'. Spot 90 sx cmt plug 336' to surface.
12. Top 7" csg with 10 sx cmt.
13. Cut off Braden Head. Weld on PxA marker.
14. Restore surface.

Please call Cindy Borton at
303-830-5119 if you have any
questions.

14. I hereby certify that the foregoing is true and correct

Signed

J Hampton

Title Sr. Staff Admin. Supv

Date

11/30/90

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

AMOCO