



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

TONY ANAYA  
GOVERNOR

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

December 7, 1983

Mr. James Smith  
Southland Royalty Co.  
Drawer 570  
Farmington NM 87499

Re: Reid A #1, A-13-29N-10W  
Moore #3, J-35-32N-12W  
Calloway #2, A-22-31N-11W

Dear Smitty:

Open flow packer leakage retests on the referenced wells indicate a tubing or packer leak. In order to comply with Rule 112-A and the order authorizing the multiple completion you are directed to take remedial action as soon as possible. I realize you repaired the packer at the Reid A #1 recently, but it apparently did not solve the problem.

If you have any questions please contact this office.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson  
Deputy Oil and Gas Inspector

CG/lh

cc: Well Files