

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		87 JUL 10 AM 10:30	
2. NAME OF OPERATOR Solar Petroleum, Inc.		FARMINGTON RESOURCE AREA FARMINGTON, NEW MEXICO	
3. ADDRESS OF OPERATOR 1099 18th St. Suite 2900 Denver, Co. 80202		8. FARM OR LEASE NAME Navajo Tribe of Indians F	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Sec 9 T31N R17W 1310 FNL 2600 FWL		9. WELL NO. 163	
14. PERMIT NO.		15. ELEVATIONS (Show whether DP, RT, OR, etc.) 5230 GR	
		10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup - Gallup	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 9 T31N R17W	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We request approval to plug and abandon this well. The well was TA'd 6-19-87 as follows:

6-19-87 Ran tbg to 967' and pumped 25 sx cmt. Pulled tbg to 747'. Displace with non-corrosive fluid. Pulled tbg and shut in at surface.

To plug and abandon this well, we will tag TD and check bottom plug. If plug has slipped we will re install a new plug. If bottom plug is in place we will go up hole and install surface plug of 25 sx cmt spotted by tbg. at least 100' from surface. Restore location.

18. I hereby certify that the foregoing is true and correct

SIGNED Mari O'Keefe 7687

TITLE Engineering Technician

DATE 6-29-87

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side