## Go by & Check this location.

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

- MALTILLE DINE	in the second	j	API # (assigned by OCD)	
Type of We.	Sundry Notices and the press.	:	30-045-26583 5. <b>Lease Number</b>	
GAS			Fee 6. State Oil&Gas Lease	
. Name of Ope			7. Lease Name/Unit Name	
MERIDI	AN OIL		Wilmuth	
Balalana C 1	Phone We of Occuptor	<u> </u>	8. Well No. 1A	
	Phone No. of Operator 89, Farmington, NM 87499 (505) 326-9700	0 !	9. Pool Name or Wildcat Blanco PC/Blanco MV	
. Location o:	f Well, Footage, Sec., T, R, M	<del></del>	10. Elevation:	
	00'FEL, Sec.26, T-31-N, R-11-W, NMPM, Sa	an Juan Count <b>y</b>		
Type of Sul	omission Type of i	Action		
Not	tice of Intent Abandonment	Change of	Plans	
X Subsequent Report Plugging Back		New Const:	New Construction	
_^_ 541	Casing Repair	Non-Routin	t off	
Fi	nal Abandonment — Odsing Kepuir Altering Casing			
<del></del>	_X_ Other - Bradenh		-	
.3. Describe	e Proposed or Completed Operations			
4-9-95	MIRU. Ran gauge ring into Mesaverde ti		H. NU BOP. TOOH	
4-9-95 4-10-95	w/1 1/4" tbg. TOOH w/2 3/8" tbg & p}	kr. SDON. @ 2300'. TOOH. DK. Dump 2 sx s @ 495'. RU. Es calcium chlori	TIH, load hole w/1% sd on top of RBP. Ran stablish injection.	
	<pre>w/1 1/4" tbg. TOOH w/2 3/8" tbg &amp; p) RU, ran gauge ring to 2350'. Set RBP KCl wtr. PT csg &amp; RBP to 1000 psi, C CBL @ 0-2295', TOC @ 500'. Perf csg Pump 195 sx Class "B" neat cmt w/2% wtr. Circ 16 bbl cmt to surface. WOC TOOH. TIH, tag cmt @ 450'. Drill cmt</pre>	cr. SDON. @ 2300'. TOOH. DK. Dump 2 sx s @ 495'. RU. Es calcium chlori C. @ 450-505'. PT	TIH, load hole w/1% sd on top of RBP. Ran stablish injection. ide. Displace w/16 bbl csg to 1000 psi, OK.	
4-10-95	<pre>w/1 1/4" tbg. TOOH w/2 3/8" tbg &amp; p) RU, ran gauge ring to 2350'. Set RBP KCl wtr. PT csg &amp; RBP to 1000 psi, ( CBL @ 0-2295', TOC @ 500'. Perf csg Pump 195 sx Class "B" neat cmt w/2% wtr. Circ 16 bbl cmt to surface. WOC TOOH. TIH, tag cmt @ 450'. Drill cmt TIH to top of RBP @ 2300'. Circ out TIH, tag fill @ 4970'. CO @ 4970-5057 J-55 tbg, landed @ 4953'. Set Model</pre>	Rr. SDON.  2300'. TOOH.  2495'. RU. Escalcium chlori  450-505'. PT  sd. TOOH. TIH W.  "F" pkr @ 2546	TIH, load hole w/1% sd on top of RBP. Ran stablish injection. ide. Displace w/16 bbl csg to 1000 psi, OK. P. TIH to 2900'. SDON. /77 jts 2 3/8" 4.7# 6'. TOOH. TIH w/79 jts	
4-10-95 4-11-95 4-12-95	<pre>w/1 1/4" tbg. TOOH w/2 3/8" tbg &amp; p) RU, ran gauge ring to 2350'. Set RBP KCl wtr. PT csg &amp; RBP to 1000 psi, C CBL @ 0-2295', TOC @ 500'. Perf csg Pump 195 sx Class "B" neat cmt w/2% wtr. Circ 16 bbl cmt to surface. WOC TOOH. TIH, tag cmt @ 450'. Drill cmt TIH to top of RBP @ 2300'. Circ out TIH, tag fill @ 4970'. CO @ 4970-5057</pre>	Rr. SDON.  2300'. TOOH.  2495'. RU. Escalcium chlori  450-505'. PT  sd. TOOH. TIH W.  "F" pkr @ 2546	TIH, load hole w/1% sd on top of RBP. Ran stablish injection. ide. Displace w/16 bbl csg to 1000 psi, OK. P. TIH to 2900'. SDON. /77 jts 2 3/8" 4.7# 6'. TOOH. TIH w/79 jts H.	
4-10-95 4-11-95 4-12-95	<pre>w/1 1/4" tbg. TOOH w/2 3/8" tbg &amp; p) RU, ran gauge ring to 2350'. Set RBP KCl wtr. PT csg &amp; RBP to 1000 psi, C CBL @ 0-2295', TOC @ 500'. Perf csg Pump 195 sx Class "B" neat cmt w/2% wtr. Circ 16 bbl cmt to surface. WOC TOOH. TIH, tag cmt @ 450'. Drill cmt TIH to top of RBP @ 2300'. Circ out TIH, tag fill @ 4970'. CO @ 4970-5057 J-55 tbg, landed @ 4953'. Set Model 1 1/4" 2.33# IJ tbg, landed @ 2467'.</pre>	Rr. SDON.  2300'. TOOH.  2495'. RU. Escalcium chlori  450-505'. PT  sd. TOOH. TIH W.  "F" pkr @ 2546	TIH, load hole w/1% sd on top of RBP. Ran stablish injection. ide. Displace w/16 bbl csg to 1000 psi, OK. P. TIH to 2900'. SDON. /77 jts 2 3/8" 4.7# 6'. TOOH. TIH w/79 jts	
4-10-95 4-11-95 4-12-95	<pre>w/1 1/4" tbg. TOOH w/2 3/8" tbg &amp; p) RU, ran gauge ring to 2350'. Set RBP KCl wtr. PT csg &amp; RBP to 1000 psi, C CBL @ 0-2295', TOC @ 500'. Perf csg Pump 195 sx Class "B" neat cmt w/2% wtr. Circ 16 bbl cmt to surface. WOC TOOH. TIH, tag cmt @ 450'. Drill cmt TIH to top of RBP @ 2300'. Circ out TIH, tag fill @ 4970'. CO @ 4970-5057 J-55 tbg, landed @ 4953'. Set Model 1 1/4" 2.33# IJ tbg, landed @ 2467'.</pre>	Rr. SDON.  2300'. TOOH.  2495'. RU. Escalcium chlori  450-505'. PT  sd. TOOH. TIH W.  "F" pkr @ 2546	TIH, load hole w/1% sd on top of RBP. Ran stablish injection. ide. Displace w/16 bbl csg to 1000 psi, OK. P. TIH to 2900'. SDON. /77 jts 2 3/8" 4.7# 6'. TOOH. TIH w/79 jts H.	
4-10-95 4-11-95 4-12-95	<pre>w/1 1/4" tbg. TOOH w/2 3/8" tbg &amp; p) RU, ran gauge ring to 2350'. Set RBP KCl wtr. PT csg &amp; RBP to 1000 psi, C CBL @ 0-2295', TOC @ 500'. Perf csg Pump 195 sx Class "B" neat cmt w/2% wtr. Circ 16 bbl cmt to surface. WOC TOOH. TIH, tag cmt @ 450'. Drill cmt TIH to top of RBP @ 2300'. Circ out TIH, tag fill @ 4970'. CO @ 4970-5057 J-55 tbg, landed @ 4953'. Set Model 1 1/4" 2.33# IJ tbg, landed @ 2467'.</pre>	Rr. SDON.  2300'. TOOH.  2495'. RU. Escalcium chlori  450-505'. PT  sd. TOOH. TIH W.  "F" pkr @ 2546	TIH, load hole w/1% sd on top of RBP. Ran stablish injection. ide. Displace w/16 bbl csg to 1000 psi, OK. P. TIH to 2900'. SDON. /77 jts 2 3/8" 4.7# 6'. TOOH. TIH w/79 jts H.	

(This space for State Use)
Approved bigriginal Signed by FRANK T. CHAVEZ TitleSUPERVISOR DISTRICT #Date APR 1 9 1995