Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Expires.	IVIAI CII J	11, 1777
 D. Maria		01 - 1 NT -

BUREAU OF LAND MANAGEMENT			
CUNIDDY NOTICES AND DEDOTS ON WELLS			
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7. If Unit or CA, Agreement Designation		
IN TRIPLICATE			
2 2 1839	8. Well Name and No.		
(0)   [C(0) 1)   (0)	SJ 32-7 Unit #207		
Phillips Petroleum Company			
3. Address and Telephone No.			
	10. Field and Pool, or exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			
Unit N, 1230' FSL & 1570' FWL Section 27, T32N, R7W			
Section 27, 132N, K/W			
N TO INDICATE NATURE OF NOTICE REPORT	San Juan, NM   NM   NM   NM   NM   NM   NM   NM		
I I INDICATE NATURE OF NOTICE, HE OF I	, ON OTHER BATTA		
TYPE OF ACTION			
Abandonment	Change of Plans		
Recompletion	New Construction		
Plugging Back	Non-Routine Fracturing		
Casing Repair	Water Shut-Off		
Altering Casing	Conversion to Injection		
X Other Replace PC Pump	Dispose Water (Note: Report results of multiple completion on W		
	Completion or Recompletion Report and Log form		
rque anchor, 2-7/8" exp. check, then 025 PC "F" nipple set @ 3301', then 109 jts 2-3/8"	Pump (stator) top set @ tubing.		
Sr. Regulatory/Proration Cler	k Date 12/14/99		
	IN TRIPLICATE  IN TRIPLICATE  UEC 2 2 1999  OILL GOING DIVO  DISTINATION  TYPE OF ACTION  Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing  X Other Replace PC Pump  Altering Casing ertinent to this work.)*  Ted on the subject well had to be replaced.  Programment of the subject well had to be replaced.  Type of Action of the subject well had to be replaced.  Trical depths for all markers and zones pertinent to this work.)*  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.  The completion of the subject well had to be replaced.		

\* See Instruction on Reverse Side

DEC 20 1999