

Riddle Gas Com C #1

K-30-31N-09W

AMOCO PRODUCTION CO.

F

30-045-27790

05-07-90

F. Loc. 2120/S; 890/W Elev. 6641 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ Gas
Csg. Perf. Prod. Stim.T
R
A
N
SI.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. Gas
1st Del. Oil

TOPS	NTD	Well Log	TEST DATA							Ref.No.
Ojo Alamo	C-103	Plat	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104	Electric Log								
Fruitland		C-122								
Pictured Cliffs	Ditr	Dfo								
Chacra	Datr	Dac								
Cliff House	NSH, NSP, DD order R-9310 W/299.10 Acres									
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

P
o
o

BasinFrCoal Co. SJ S 30 T 31N R 09W U K Oper. Amoco Production Co. Lse. Riddle Gas Com C No. 1



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LAPLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO:

SF-080243 et. al. (WC)
3162.3-1.0 (019)

JUL 18 1991

Amoco Production Company
PO Box 800
Denver, Colorado 80201

Gentlemen:

RECEIVED

JUL 19 1991

**OIL CON. DIV.,
DIST. 3**

Enclosed are your Applications for Permit to Drill well Nos.:

1. No. 3 Florance Gas Com I, sec. 18, T 30 N, R 9 W, SF-080243
2. No. 3 Florance "AA", sec. 8, T 30 N, R 9 W, SF-078129-A
3. No. 3 Florance "AE", sec. 25, T 30 N, R 10 W, SF-080776
4. No. 7 Florance "AD", sec. 24, T 30 N, R 10 W, SF-078116
5. No. 9 Riddle "H", sec. 17, T 30 N, R 9 W, SF-080244
6. No. 5 Elmer E. Elliott "A", sec. 15, T 30 N, R 9 W, SF-078139
7. No. 3 Giomi Gas Com "C", sec. 28, T 30 N, R 9 W, SF-078042
8. No. 1 Walker Gas Com A, sec. 31, T 31 N, R 9 W, SF-078316-F
9. No. 1 Riddle Gas Com C, sec. 30, T 31 N, R 9 W, SF-078319-A

All of the above referenced wells are located in San Juan County, New Mexico. As Discussed with Cindy Burton of your company on June 27, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

9 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec,
NM 87410

ABANDONED LOCATION