



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO:

NM-0607 et al. (WC)
3162.3-1 (019)

RECEIVED

OCT 4 1991

OCT. 03 1991

ARCO Oil and Gas Company
P.O. Box 1610
Midland, TX 79702

OIL CON. DIV
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 1 Atlantic Fruitland 3 Com, sec. 3, T. 30 N., R. 10 W., San Juan Co., NM, lease NM-0607.
2. 2 Atlantic Fruitland 3 Com, sec. 3, T. 30 N., R. 10 W., San Juan Co., NM, lease SF-080917.
3. 1 Atlantic Fruitland 4, sec. 4, T. 30 N., R. 10 W., San Juan Co., NM, lease SF-080917.
4. 2 Atlantic Fruitland 4, sec. 4, T. 30 N., R. 10 W., San Juan Co., NM, lease SF-080917.
5. 1 Atlantic Fruitland 5, sec. 5, T. 30 N., R. 10 W., San Juan Co., NM, lease SF-080917.
6. 2 Atlantic Fruitland 5, sec. 5, T. 30 N., R. 10 W., San Juan Co., NM, lease SF-080917.
7. 1 Atlantic Fruitland 25, sec. 25, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-013688.
8. 2 Atlantic Fruitland 26, sec. 26, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.
9. 1 Atlantic Fruitland 27, sec. 27, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.
10. 2 Atlantic Fruitland 27, sec. 27, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.

ABANDONED LOCATION

- ✓ 11. 1 Atlantic Fruitland 28, sec. 28, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.
- ✓ 12. 2 Atlantic Fruitland 28, sec. 28, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-0606.
- 13. 1 Atlantic Fruitland 33, sec. 33, T. 31 N., R. 10 W., San Juan Co., NM, lease SF-080917.
- 14. 2 Atlantic Fruitland 33, sec. 33, T. 31 N., R. 10 W., San Juan Co., NM, lease SF-080917.
- 15. 1 Atlantic Fruitland 34, sec. 34, T. 31 N., R. 10 W., San Juan Co., NM, lease SF-080917.

As discussed with Ken Gosnell of your company on, September 26, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

~~New Mexico Oil Conservation~~ 00 Rio Brazos Rd., Aztec, NM 87410