## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

APF * (essigned by OCD) 30-045-29363 1-046-29363 1-046			Sundry Notices	and Reports on W	ells	
Allison Unit  8. Well No.  #145  PO Box 4289, Farmington, NW 87499 (505) 326-9700  9. Pool Name or Wildcat Basin Fruitland Coal  1. Location of Well, Footage, Sec., T, R, M  875' FSL, 920' FWL, Sec.7, T-32-N, R-6-W, NMPM, San Juan County  Type of Submission  Type of Submission  Abandonment  Abandonment  Plugging Back  Plugging Back  Non-Routine Fracturing  Casing Repair  Altering Casing  Conversion to Injection  3-11-99  MIRU. TOOH w/rods & pump. ND WH. NU BOP. SDON.  3-12-99  TOOH w/tbg. TIH w/3 7/8" bit. Unload well, wash to PBTD @ 3133'. TOOH w/bit. TiH w/99 jts 2 3/8" 4.7# J-55 tbg, set @ 3112'. ND BOP. NU WH.  TIH w/one 2" x 1 w' x 10' x 14' Rhac-2 pump & rods.  PT to 500 psi, OK.  3-15-99  RD. Rig released.  SIGNATURE Albert March 22, 1999  vkh  (This space for State Use)	1. Type of Well GAS			2 4 1990 H	30-045- 5. <b>Lease 1</b> FEE	-29363 Number
8. Well No. #145 PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. Pool Name or Wildcat Basin Fruitland Coal 4. Location of Well, Footage, Sec., T, R, M 875' FSL, 920' FWL, Sec.7, T-32-N, R-6-W, NMPM, San Juan County  Type of Submission    Notice of Intent   Abandonment   Change of Plans   Recompletion   New Construction   New Construction   Ne		IGTQN	(O)[	VII CON DIV		
Notice of Intent Abandonment Chage of Plans Recompletion New Construction Non-Routine Fracturing Recompletion Non-Routine Fracturing Water Shut off Altering Casing Conversion to Injection  3-11-99 MIRU. TOOH w/rods & pump. ND WH. NU BOP. SDON. 3-12-99 TOOH w/tbg. TIH w/3 7/8" bit. Unload well, wash to PBTD @ 3133'. TOOH w/bit. TiH w/one 2" x 1 %" x 10' x 14' Rhac-Z pump & rods. PT to 500 psi, OK. Pump action, OK. 3-15-99 RD. Rig released.  SIGNANURE Jump March 22, 1999 vkh  (This space for State Use)	PO Box 4289,	ne No. of Operat Farmington, NM	87499 (505) 326		8. Well No #145 9. Pool Na Basin 1	o. mme or Wildcat Fruitland Coal
3-11-99 MIRU. TOOH w/rods & pump. ND WH. NU BOP. SDON. 3-12-99 TOOH w/tbg. TIH w/3 7/8" bit. Unload well, wash to PBTD @ 3133'. TOOH w/bit. TIH w/99 jts 2 3/8" 4.7# J-55 tbg, set @ 3112'. ND BOP. NU WH. TIH w/one 2" x 1 w" x 10' x 14' Rhac-Z pump & rods. PT to 500 psi, OK. Pump action, OK. 3-15-99 RD. Rig released.  SIGNATURE Lingua Shill fire A Regulatory Administrator March 22, 1999 wkh (This space for State Use)	Notic _X_ Subse	e of Intent quent Report	Abandonment Recompletio Plugging Ba Casing Repa Altering Ca	Change o  New Cons ck Non-Rout ir Water Sh sing Conversi	truction ine Fracturi ut off	-
(This space for State Use)	3-11-99 3-12-99	MIRU. TOOH w/r TOOH w/tbg. TI w/bit. TIH w TIH w/one 2" Pump action,	ods & pump. ND W H w/3 7/8" bit. /99 jts 2 3/8" 4. x 1 4" x 10' x 14 OK.	Unload well, wash .7# J-55 tbg, set	n to PBTD @ @ 3112'. N	D BOP. NU WH.
· ·			id Regulator	ry Administrator	Ma:	
	ORIGIN			TY OIL & GAS INSPECTOR,	DIST. #3	MAR 24 1999