

Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 073051

Unit W/2 Sec. 34, T. 32N
R. 11W S. 4E. 7.4.

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

JUN 13 1952

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 2, 1952

Well No. 51 is located 1550 ft. from N line and 1025 ft. from W line of sec. 34

W/2 of 34 32 North 11 West N. 7.4.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. Will be furnished later.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to drill with rotary tools to top of Cliff House sand - set pipe - and drill with rotary using gas through Cliff House, Menefee & Point Lookout if available - if not, cable tools - shoot - clean out for gas completion in Mesa Verde formation.

Casing Program:

- 150' - 9 5/8" cemented to surface
- 4500' - 7" 20# J-55 cemented w/200 lbs.
- 5200' - 2" Tubing



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kenneth Murchison

Address 1105 Reserve Loan Life Building

Dallas, Texas

By E. J. Cosinger
S. I. Cosinger
Title Superintendent