

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS		5. LEASE DESIGNATION AND SERIAL NO.	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		14-20-603-592	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR		Navajo Tribal	
3. ADDRESS OF OPERATOR		7. UNIT AGREEMENT NAME	
P. O. Box 507, Farmington, New Mexico 87401 2 1968		8. FARM OR LEASE NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		Navajo Unit "B"	
1980' FSL and 660' FWL		9. WELL NO.	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		Four Corners Paradox	
4834' D.F.		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA	
		29-32N-20W	
		12. COUNTY OR PARISH	
		San Juan	
		13. STATE	
		N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On September 4, 1968 it is proposed to plug and abandon as follows:

Cut off 5 1/2" casing at 3000' and pull from well.

Run 2" tubing to bridge plug at 3572' and spot 15 sax cement from 3572 to 3450.


Pull tubing to 3020' and spot 150 sax cement from 3020 to 2370.

Pull tubing tubing from hole and bradenhead squeeze.

Place cement plug from 10' to surface and erect marker.

18. I hereby certify that the foregoing is true and correct

SIGNED



TITLE Operator

DATE 9-2-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

SEP 2 1968

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY