

TOLEDO

19-48084-2

MARK | FOLD

16-43094-2 U. S. GOVERNMENT PRINTING OFFICE

Drawing size	Box foot height	Inch thickness per foot	Flare	Amount	Kind of shoe	Cut and pulled from	From		Inches
							3.0	Perforated	

After cementing 4-1/2" casing, cement plug was drilled out to total depth. Filled hole to 1080' with sand and treated open hole from 1045' to 1080' with 21,650 gallons of lease crude oil with 1.2# sand per gallon of oil. Well sanded off after 7740 gallons of treatment and flowed back 1400 gallons of treatment material. Cleaned well out to total depth and installed pumping equipment. After recovering all but 128 barrels of load oil, well sanded up and sand pump was used to clean out sand. Continued pumping well several days before recovering all of load oil. After recovering load oil, well pumped 8 barrels of oil in 24 hours on test ending 9:00 A.M., 12-28-61. OIL OK GAS SANDS OK SOME

Date 19 JAN 31 1968 JMS OFFICE OF THE DIRECTOR

The information given hereafter is a complete and correct record of the work and all work done thereon.

(Faint header information at the top of the page)

LESSOR OF TRACT _____ E1619 _____ State _____

Company: 127000 INC. Address: Box 510, Escondido, CA 92025

LOCATE MEET CORRECTLY

[illegible]

GEOLOGICAL SURVEY

LEASE OR PERMIT TO PROSPECT

SERIAL NUMBER

0.2. GUID OFFICE

BUCKET BULGARI NO. 43-B322-1
EOLIN 98810460