

State
(SUBMIT IN TRIPLICATE)

Indian Agency Ute Mountain Tribe

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1-22-Ind-9772

Allettee _____

Lease No. _____

Barber Dome

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	<u>NOV 3 1961</u>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
<u>Notice of Intention to Workover</u>	<u>XX</u>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 1, 1961

Well No. 19 is located 275 ft. from [N] line and 1364 ft. from [E] line of sec. 21

NE/4 Sec. 21
(1/4 Sec. and Sec. No.)

32N
(Twp.)

14W
(Range)

N.M.P.M.
(Meridian)

Barber Dome
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)


The elevation of the derrick floor above sea level is 6457 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is intended to workover this well in the following manner:

1. Move in Workover Rig.
2. Kill well with salt water.
3. Pull top section of tubing.
4. Run over-shot and retrieve fish.
5. Trip to inspect tubing. Replace bad joints, or tubing string.
6. Run tubing and nipple up.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 990

Farmington, New Mexico

By Original Signed D. W. Meehan

Title Petroleum Engineer