

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

Box 4289, Farmington, New Mexico 874994289

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1100'S, 1000'W

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Present Status

SUBSEQUENT REPORT OF:

RECEIVED

NOV 30 1982

GRAND JUNCTION, CO

5. LEASE

I-22-Ind-2772

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Ute Indian

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Ute

9. WELL NO.

6

10. FIELD OR WILDCAT NAME

Barker Creek Paradox

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-32-N, R-14-W

N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6211' GL

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was reviewed and is in mechanical condition to recompleat in the following possible zones:

Depth	Zone	Est. Reserves (BCFG)
8445-75	Barker Creek-1st Sour	3.84
8123-35	Desert Creek-3rd Sweet	1.28
7910-20	Hermosa	1.28

Due to present market conditions, the unavailability of the Pipeline Connection to handle additional sour gas, and the cost to recompleat and test each zone listed above it is uneconomical to recompleat this wellat this time. It is requested to leave this wellbore in its present shut in status.

Subsurface Safety Valve: Manu. and Type

Set @

18. I hereby certify that the foregoing is true and correct

SIGNED Ray A. Smith TITLE Petroleum Engr DATE November 19, 1982

APPROVED BY John L. Price (This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY: TITLE District Supervisor DATE 11/30/82

SHUT-IN WELL DATA SHEET

Lease Ute, Well No. 6, SW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 17,
T. 32, R. 14, County San Juan, State New Mexico.
Formation: Barker Creek Paradox Interval: 8546 to 8612.

1. Date of Completion: 2-6-51; I.P. 8993 ^{MCFPD}~~BOPD~~
2. Date of Last Test: (a) n/a; Shut-in Pressure: n/a psig;
24 Hour Rate: n/a BOPD; MCFPD n/a
Working Pressure: n/a psig; Water Vol. n/a BOPD
3. Is well capable of producing hydrocarbons in paying quantities? no.
Estimated current daily producibility: _____
Estimated lift cost: \$ _____/bbl.

4. Reason for Not Producing and/or Reason Not to Plug and Abandon: (*)

*(If not capable of producing in paying quantities.) (b)

This well has high lifting costs to remove water and high transportation costs to dispose of the water. This well is being reviewed for possible recompletion in another productive zone or used as a water disposal well.

5. Date producer was shut-in and reason for shut-in status (c)

April, 1958. Non productive - high salt water/gas ratio

6. Additional information: (d)

RECEIVED
SEP 29 1982

MINERALS MANAGEMENT SERV
DURANGO, CO

(See reverse side for instructions)

Instructions for Data Sheet

- (a) If tests have not been taken on referenced well subsequent to _____, you are requested to make arrangements to obtain a stabilized production test and report the results to this office within 30 days, as needed to establish commercial value under 43 CFR 3107.3-2.
- (b) Reasons for Not Producing: No market outlet; high transportation costs; high lifting costs; court problems; Government order, etc.
- Reasons Not to Abandon: More evaluation needed; deeper drilling plans; offset development needed, etc.
- (c) Reason for Suspending Operations: Mechanical failures; high water/oil ratios; low productivity, etc.
- Reason for Maintaining Shut-in Status: Secondary recovery plans; water disposal plans; additional engineering and workover programs, etc.
- (d) Additional Information: Give reasons for not continuing lease development. Indicate probable well status changes. Show estimated reserves, etc.