In Lieu of Form 3160-5 (June 1990)

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use APPLICATION FOR

DO 1101 450 1		ior proposais	 to deepe
PERMIT-"	for such	proposals	

5.	Lease	Designation	and	Serial N	lo.
		•			

14-20-603-585


If Indian, Allottee or Tribe Name

		Navajo
	SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1.	Type of Well  ☑Oil Well ☐ Gas Well ☐ Other	8. Well Name and No. Navajo AA No. 12
2.	Name of Operator 21st Century Investment Corp.	9. API Well No. So-C45-114.3.3
3.	Address and Telephone No. C/O Walsh Engineering & Production Corp. 7415 East Main Farmington, NM 87402 505-327-4892	10. Field and Pool, or Exploratory Area North Many Rocks Gallup
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) 1532' FSL & 2600' FEL, Sec. 17, T32N, R17W	11. County or Parish, State San Juan, NM.

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Change of Plans Notice of Intent ☐ Recompletion □ New Construction ☐ Non-Routine Fracturing ☐ Plugging Back ☐ Subsequent Report ☐ Casing Repair ☐ Water Shut-Off ☐ Conversion to Injection ☐ Altering Casing ☐ Final Abandonment ☐ Dispose Water Other \_ (Note: Report results of multiple completion on Well Completion or Recompletion Report and

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well 13. is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*


21st Century Investment Corp. plans to plug and abandon the above mentioned well as per the attached procedure.



Log form.)


OIL CORL DUY.


14.	I hereby certify that the foregoing is the and correct		Variable of	State of the second of the sec	
	Signed John C. Thompso	on) Title	Agent	Date 12/05/96	
	(This space for Federal or State office use)			APPROVED	
	Approved by	Title		A Late PROVED	-
	Conditions of approval, if any:			DFC 4 5 500	



Navajo AA No. 12 1532' FSL & 2600' FEL Sec 17 T32N R17W


Current Status





## Navajo AA No. 12 1532' FSL & 2600' FEL Sec 17 T32N R17W

### P&A Status







# Plug & Abandon Procedure for 21st Century Investment Corp. Navajo AA #12

Location: Section 17 T32N R17W

San Juan County, New Mexico

Date: December 5, 1996

#### Procedure:

- 1. MOL & RU pulling unit. Haul in 2-3/8" work string. Hold safety meeting.
- 2. Blow well down and ND tubing head and NU BOP. Lay 2-3/8" flow line to pit. Pressure test BOP.
- 3. Lay down rods and/or tubing. Note: Records do not indicate what type of production strings are currently in the hole, ie. tubing, rods, pumps, etc.
- 4. PU cement retainer & TIH on 2-3/8" tubing. Set cement retainer at 1540' (100' above Gallup perforations).
- 5. Mix and pump 26 sx (31 cu.ft.) of cement. Sting out of cement retainer & TOH.
- 6. Perforate 2 holes in 4-1/2" casing at 100'.
- 7. Circulate 36 sx (43 cu. ft.) of cement down 4-1/2" and up 7" x 4-1/2" annulus through perfs at 100".
- 8. ND BOP and cut off well head below surface casing. Install P&A marker. Rig down & release rig.
- 9. Clean location and restore as per BLM requirements.

Note: All cement volumes are calculated w/ 100% excess.

John C. Thompson

Engineer