

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION & SERIAL NO. 14-20-603-585	
2. NAME OF OPERATOR James P. Woosley		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribe	
3. ADDRESS OF OPERATOR P.O. Drawer 1480, Cortez, CO 81321		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1720' FSL & 460' FWL At proposed prod. zone Same Same		8. FARM OR LEASE NAME Navajo AA	
14. PERMIT NO.		9. WELL NO. #7	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5615' GL		10. FIELD AND POOL, OR WILDCAT No. Many Rocks Lower Gallu	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NW $\frac{1}{4}$ SW $\frac{1}{4}$ Sec. 17-T32N-R17W	
		12. COUNTY San Juan	13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON ☒
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other)

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work

* Must be accompanied by a cement verification report.

Plan to plug as follows:

1. Place cement plug across and 100' above perforations 255x
(Notched w/abrasi jets at 1664-1666')
2. Place cement from 100' below surface to surface. 255x
3. Clean up, disc & reseed location.

RECEIVED
BLM MAIL ROOM

88 APR -4 PM 1:22

FARMINGTON RESOURCE AREA
FARMINGTON NEW MEXICO

RECEIVED
APR 13 1988
OIL CON. DIV.
DIST. 3

19. I hereby certify that the foregoing is true and correct

SIGNED

James P. Woosley

TITLE

Operator

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
DATE 3/29/88
AS AMENDED

APR 02 1988

AREA MANAGER

NMOCC