

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports of Wells

1. Type of Well
GAS

2. Name of Operator

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

560' FSL, 315' FWL, Sec. 11, T-32-N, R-14-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment

Type of Action

☐ Abandonment ☐ Change of Plans
☐ Recompletion ☐ New Construction
☐ Plugging Back ☐ Non-Routine Fracturing
☒ Casing Repair ☐ Water Shut off
☐ Altering Casing ☐ Conversion to Injection
☐ Other -

13. Describe Proposed or Completed Operations

2-26-98 MIRU. Pump 3000 gal 28% Hcl down tbq. Displace w/20 bbl 2% Kcl wtr. TIH w/gauge ring to 3223'. TOO H. Load hole w/4 bbl wtr. Pressure up to 2000 psi. Attempt to PT secondary seal on 7" csg, failed. SDON.

2-27-98 ND WH. Circ hole clean. Cut end off 7" stub. Weld new stub on. NU BOP. PT secondary seal to 1000 psi, OK. TOO H w/pkr & 98 jts 2 7/8" tbq. SDON.

2-28-98 TIH, tag up @ 4108'. Circ hole clean to 4154'. TOO H. TIH w/7" RBP, set @ 3651'. Pressure up backside to 400 psi. TOO H. Load hole w/fluid. Pressure up csg to 400 psi. TIH w/7" FB pkr, set @ 988'. PT 7" csg @ 0-988', OK. Reset pkr @ 2309'. PT csg @ 0-2955' to 550 psi, OK. PT csg @ 2955-3651', failed. Reset pkr @ 3628'. PT csg @ 0-3628', failed. SDON.

3-1-98 PT csg to 400 psi, failed. Isolate hole 7" csg @ 3100-3114'. TOO H w/FB pkr. TIH w/retrieving tool. TOO H w/RBP. TIH w/7" CIBP, set @ 3670'. PT csg to 400 psi, failed. TOO H. SDON.

3-2-98 SD for rig repairs. (Verbal approval to do emergency csg repair from Dan Rabinowitz, BLM & Ernie Busch, OCD).

3-3-98 Pump 225 sx Class "B" neat cmt @ 2400-3670'. Reverse circ 30 bbl wtr, no cmt. TOO H. Sqz to 200 psi. WOC. SDON.

3-4-98 TOO H. TIH, tag TOC @ 2857'. Drill cmt @ 2857-3125'. PT csg to 400 psi/10 min, OK. Drill cmt @ 3125-3285'. PT csg to 400 psi, OK. Drill cmt @ 3285-3350'. SDON. (Verbal approval to set pkr @ 3185' from Dan Rabinowitz, BLM & Ernie Busch, OCD).

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 3/24/98

(This space for Federal or State Office use)

APPROVED BY ACM Title FOR RECORD

CONDITION OF APPROVAL, if any:

Date _____

TC 5/12/98

RECORDED

- 3-5-98 Drill cmt @ 3350-3551'. TOO. TIH to 3551'. Pump 10 sx Class "B" neat cmt. TOO. WOC. SDON. (Verbal approval to change plans from Jim Lovato, BLM & Ernie Busch, CCD).
- 3-6-98 TIH w/mill to TOC @ 3469'. Drill cmt @ 3469-3526'. SDON.
- 3-7-98 Mill cmt @ 3526-3606'. Reverse circ tbg. PT csg to 800 psi/5 min, OK. SDON.
- 3-8-98 Drill cmt @ 3605-3670'. Circ hole clean. PT csg to 400 psi, OK. Circ hole clean. SDON.
- 3-9-98 Displace hole w/2% Kcl wtr. Mill CIBP @ 3670'. Circ hole clean to PBTD @ 4161'. TOO. TIH w/pkr & 98 jts 2 7/8" 6.5# J-55 EUE tbg: landed tbg @ 3226', set pkr @ 3214'. ND BOP. NU WH. PT 7" csg to 300 psi, OK. SDON.
- 3-10-98 PT 7" csg to 320 psi/60 min, OK. RD. Rig released. (Gary Rutherford, BLM & Ernie Busch, OCD witnessed PT).