

March 25, 1973

14017-21706

F. Loc. 14017-21706 Elev. 5375 Spd. _____ Comp. _____ TD _____ PB _____

Casing S. _____ W. _____ Sx. _____ Int. _____ W. _____ Sx. Pr. _____ W. _____ Sx. T. _____
Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

I.P. _____ BO/D _____ MCF/D _____ After _____ Hrs. _____ SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. _____ s _____

TOPS		NITD	Well Log	TEST DATA							Ref. No.
Kirtland		C-103	Plat	Schd.	PC	Q	PW	PD	D		
Fruitland		C-104	Electric Log								
Pictured Cliffs			C-122								
Cliff House		Ditr	Dfa								
Menefee		Datr	Dac								
Point Lookout		ABANDONED LOCATION									
Mancos											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											

P
O
O

14017-21706 Co. S 12 T 22 R 17W U Oper. by _____ Lsec. 14017-21706

No.

Drawer 600
Farmington, New Mexico 87499

JUL 8 1983

CERTIFIED P 272 299 435

Dugan Production Corporation
P. O. Box 208
Farmington, New Mexico 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

Nos. 3, 4 and 6 Hogan, SW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 30, NE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 31, NE $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 32, and SW $\frac{1}{4}$ NE $\frac{1}{4}$ sec. 32, respectively.

Nos. 3, 5, 6, 7 and 8 Horseshoe, SW $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 32, NE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 32, SE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 32, SE $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 30, SW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 32, respectively.

All located in T. 32 N., R. 17 W., San Juan County, New Mexico, lease 14-20-003-586.

The subject APDs are rescinded and returned as requested in our phone conversation of June 30, 1983, with Fran and Jim Jacobs of your Company.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in assessment of liquidated damages.

Sincerely yours,


John H. Nelson
For Acting Area Manager

Enclosures

cc: BIA, Window Rock
NMOC
Records, MS-250
BLM, MS-410
Well file (9 Perm)
DRO 9-1

Suspense (Mason)

ABANDONED LOCATION

NM-016:SMason:CSN 7/7/83
#5018

RECEIVED
SEP 1-1983
OIL CON. DIV.
DIST. 3