Form 31-52-5 Desember iven.

or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

BUREAU OF LAND MANAGEMENT STATE 29 8/10:5	5 Lease Designation and Serial No
SUNDRY NOTICES AND REPORTS ON WELLS ARE TO TOWN	5 If Indian. Allonee or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoit. Use "APPLICATION FOR PERMIT—" for such proposals	П.
SUBMIT IN TRIPLICATE	7. If Cast or CA, Agreement Designation
1. Type of Well	P 8. Well Name and No.
Oul Gas Other 2. Name of Operator	
KIMBARK OIL & GAS	STOREY #2
1 Address and Telephone No 1660 Lincoln St., Suite 2700, Denver, Co 80264	30-045-21815 10. Field and Pool. or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	BLANCO PICTURED CLIFFS 11. County of Parish, State
1190 FSL, 940 FEL SEC 34-T32N-R11-W	SAN JUAN, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION TYPE OF ACTION	
Nouce of Intension & R. C. C. C. Abandonment	Change of Plans
Nouce of Internet Recompletion	New Construction
Subsequent Renger to Plugging Back	Non-Routine Fracturing
SEP1 2 1991 Casing Repair	Water Shut-Off
Final Abandonment Notice CON. DIV. Alternag Casing Other Note: Report results	Conversion to Injection
DIST. 3 (Note: Report results Recompletion Report	of multiple completion on Well Completion or and Log form.)
13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starri-	
	• • • •
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work >*	
This Sundry Notice will serve to amend the Sundry Notice of 8/13/91. requested and was granted approval to repair the casing leak on the operations commenced to repair the casing, it became evident that the repaired and Kimbark requested approval to P&A the well. Verbal by Ken Townsend & Erroll Becher. The following procedure is proposed.	Kimbark originally Storey #2. After e casing could not approval was given
This Sundry Notice will serve to amend the Sundry Notice of 8/13/91. requested and was granted approval to repair the casing leak on the operations commenced to repair the casing, it became evident that the repaired and Kimbark requested approval to P&A the well. Verbal by Ken Townsend & Erroll Becher. The following procedure is proposed. 1. Set cmt. retainer @ 2700' to isolate PC perfs. Squeeze 25 sx be on top of cmt retainer. (class B + 3% CaCl2) 2. Set cmt retainer @ 634'. Squeeze 100 sx Class B + 3% CaCl2 + 3%/s retainer. Bullhead 140 sx of same cement from surface to top of Bradenhead squeeze 6 sx (100% excess) down 4½"x85/8" annulus.	Kimbark originally Storey #2. After e casing could not approval was given ed os follows: low and place 25 sx x Hi Seal below
This Sundry Notice will serve to amend the Sundry Notice of 8/13/91. requested and was granted approval to repair the casing leak on the operations commenced to repair the casing, it became evident that the repaired and Kimbark requested approval to P&A the well. Verbal by Ken Townsend & Erroll Becher. The following procedure is proposed. Set cmt. retainer @ 2700' to isolate PC perfs. Squeeze 25 sx be on top of cmt retainer. (class B + 3% CaCl2) 2. Set cmt retainer @ 634'. Squeeze 100 sx Class B + 3% CaCl2 + 3#/s retainer. Bullhead 140 sx of same cement from surface to top of	Kimbark originally Storey #2. After e casing could not approval was given ed os follows: low and place 25 sx x Hi Seal below
This Sundry Notice will serve to amend the Sundry Notice of 8/13/91. requested and was granted approval to repair the casing leak on the operations commenced to repair the casing, it became evident that the repaired and Kimbark requested approval to P&A the well. Verbal by Ken Townsend & Erroll Becher. The following procedure is proposed. 1. Set cmt. retainer @ 2700' to isolate PC perfs. Squeeze 25 sx be on top of cmt retainer. (class B + 3% CaC12) 2. Set cmt retainer @ 634'. Squeeze 100 sx Class B + 3% CaC12 + 3%/s retainer. Bullhead 140 sx of same cement from surface to top of Bradenhead squeeze 6 sx (100% excess) down 4½"x85/8" annulus.	Kimbark originally Storey #2. After e casing could not approval was given ed os follows: low and place 25 sx x Hi Seal below
This Sundry Notice will serve to amend the Sundry Notice of 8/13/91. requested and was granted approval to repair the casing leak on the operations commenced to repair the casing, it became evident that the repaired and Kimbark requested approval to P&A the well. Verbal by Ken Townsend & Erroll Becher. The following procedure is proposed. 1. Set cmt. retainer @ 2700' to isolate PC perfs. Squeeze 25 sx be on top of cmt retainer. (class B + 3% CaCl2) 2. Set cmt retainer @ 634'. Squeeze 100 sx Class B + 3% CaCl2 + 3#/s retainer. Bullhead 140 sx of same cement from surface to top of 3. Bradenhead squeeze 6 sx (100% excess) down 4½"x85/8" annulus. 4. Set surface plug. 5. Cut off csg 3' below G.L. and erect dry hole marker. SEE ATTACHED FOR	Kimbark originally Storey #2. After e casing could not approval was given ed OS follows: low and place 25 sx x Hi Seal below retainer.
This Sundry Notice will serve to amend the Sundry Notice of 8/13/91. requested and was granted approval to repair the casing leak on the operations commenced to repair the casing, it became evident that the repaired and Kimbark requested approval to P&A the well. Verbal by Ken Townsend & Erroll Becher. The following procedure is proposed. 1. Set cmt. retainer @ 2700' to isolate PC perfs. Squeeze 25 sx be on top of cmt retainer. (class B + 3% CaCl2) 2. Set cmt retainer @ 634'. Squeeze 100 sx Class B + 3% CaCl2 + 3%/s retainer. Bullhead 140 sx of same cement from surface to top of 3. Bradenhead squeeze 6 sx (100% excess) down 4½"x85/8" annulus. 4. Set surface plug. 5. Cut off csg 3' below G.L. and erect dry hole marker. SEE ATTACHED FOR CONDITIONS OF APPROVAL	Kimbark originally Storey #2. After e casing could not approval was given ed OS follows: low and place 25 sx x Hi Seal below retainer.

NMOCD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United Sough any false, ficultious or fraudulent statement

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 2 Storey

CONDITIONS OF APPROVAL

: • •

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 7:45 a.m. to 4:30 p.m.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6%/gal slurry weight is to be used when using class B neat cement or when CaCl₂ is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.