Submit 3 Copies

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

to Appropriate

District Office DISTRICT I

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION	DIV	ISION

Revised 1-1-89

WELL API NO.

DISTRICT I	OIL CONSERVATION DIVISION 2040 South Pacheco Street		WELL API NO. 3	0-045-23007	
P.O. Box 1980, Hobbs, NM 88240			5. Indicate Type of Lea		
P.O. Drawer DD, Artesia, NM 88210	,		STATE	FEE X	
DISTRICT III			6. State Oil & Gas Lea	nee No	$\dashv$
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lee		
SUNDRY	NOTICES AND REPORTS ON	WELLS	Control Edition of Department of Con- cerning Control Con- trol Control Control Control Control Control Control Control Control Control Contro		
(DO NOT USE THIS FORM FO	OR PROPOSALS TO DRILL OR TO DI	EEPEN OR PLUG BACK TO	Continued to	Nome	
A DIFFEREN	NT RESERVOIR. USE "APPLICATION	FOR PERMIT"	7. Lease Name or Uni	t Agreement Name	
	ORM C-101) FOR SUCH PROPOSALS	5.)	TAFOYA		
Type of Well: OIL GAS					l
WELL WELL	(X) OTHER				_
2. Name of Operator			8. Well No.		
GREYSTONE ENERGY, INC.		1-A 9. Pool name or Wildcat			
<ol> <li>Address of Operator</li> <li>5802 HIGHWAY 64, FARMINGTON, NEW MEXICO 87401</li> </ol>		BLANCO MESAVERDE			
4. Well Location			) Feet From The F	-WLL	ine
Unit Letter F : 198	20 Feet Floir Tile 1142 - 2415			County S	.
Section 35	Township 32N Range	13W	NMPM	County S	5
	in the second of	nether DF, RKB, RT, Gr, etc.)	-	The war to drive a second of the second of t	37
11. Check	k Appropriate Box to Indica	ate Nature of Notice	, Report, or Oth	er Data	
	OF INTENTION TO:	SU	JBSEQUENT R	EPORT OF:	
PERFORM REMEDIAL WOR	K X PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLII	NG OPNS.	PLUG AND ABANDONMENT	
		CASING TEST AND	CEMENT JOB X		
PULL OR ALTER CASING		OTHER:			
OTHER:		J   "	nent dates, including es	stimated date of starting any	
12. Describe Proposed or Co proposed work) SEE	ompleted Operations (Clearly state all p RULE 1103	ertinent details, and give peru	nent dates, modumig oc		
FIND AND REPAIR	R LEAK IN PRODUCTION CAS	ING AND ATTEMPT TO	SQUEEZE CEME	NT BACK TO SURFACE.	
NO TO OFT	CEMENT BACK TO SURFACE	PERFORATE 2 HOLE	S BELOW SURFA	CE SHOE AND SQUEEZE	Ξ
BACK TO SURFACE	CE FROM THAT POINT.	, i Liki Olokie i weze			
WORK IS SCHED	ULED TO START ON OR NEA	R APRIL 15TH 1999			
VVOICE					
	mation above is true and complete to th	e hest of my knowledge and t	pelief.		
hereby certify that the inform	nation above is true and complete to the			DATE: 40 03/25/99	
SIGNATURE Cheste	12. Leal	TITLE SUPERINTEND	ENI	DATE GO USIZSISS	
TYPE OR PRINT NAME				TELEPHONE NO. (505) 632	-8056
(This space for State Use)	。 。				
OFIGINAL STA	ARTHUR TO GREEKER TO PROBER	TITLOSPUTY OIL & GAS I	MSPECTOR, DIST. NO.	DATE 3-17-9	19
APPROVED BY			_		