10. Plans for Restoration of Surface (Cont'd)

- B. Restoration Plans Production Developed:
 The reserve pit will be backfilled and restored as described under Item A. In addition, those disturbed areas not required for production will be graded to blend with the surrounding topography, and seeded, per BLM recommendations. The portion of the drill pad required for production and turning areas will be graded to minimize erosion and provide access to production facilities under inclement conditions. Following depletion and abandonment of the site, restoration procedures will be those under Item C. below.
- C. Restoration Plan No Production Developed:
 The reserve pit will be restored as described above. With no production developed, the entire surface disturbed by construction of the drilling pad will be restored. The site will be contoured to blend with the surrounding topography. The site will be seeded according to BLM recommendations. If the new access road is not required for other development plans, it will be obliterated and restored and seeded per BLM recommendations.
- D. Rehabilitation Time Table:
 Upon completion of operations the intial clean up of the well site will be performed. Final restoration of the site will be performed as soon as possible according to procedural guidelines published by the USGS and BLM. Seeding of the disturbed areas which are no longer required will be performed during the appropriate season, following final restoration.

11. Other Information

- A. Surface Description:

 The surface description of the proposed location is relatively flat, with many cedar trees and sagebrush throughout.
- B. Surface Use Activities:
 The surface is federally owned and managed by the BLM. The predominant surface use is mineral exploration and production.
- C. Proximity of Water, Dwellings and Historical Sites:
 - Water: There are no reservoirs or streams in the immediate area.
 - Occupied Dwellings: There are no occupied dwellings or buildings in the area.
 - An archeological reconnissance has been performed for this location and clearance has been granted. This location had too much snow cover on it and archeological clearance will be granted when a re-survey is done by the archeologist when the snow melts.