

F

30-045-27436

7-26-89

F. Loc. 1000/S; 790/W Elev. 6134 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS	NIID	X	Well Log	TEST DATA							Ref. No.
Ojo Alamo	C-103		Plot	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104		Electric Log								
Fruitland			C-122								
Pictured Cliffs	Ditr		Dfa								
Chacra	Dalr		Dac								
Cliff House	S/336.40 Acres										
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											

P
o
o

BasinFrCoalCo. SJ s 11 t 32N R 12W U M Oper. Southland Royalty Co. Lse. Hubbard

No. 100

Hubbard #100

M-11-32N-12W

SOUTHLAND ROYALTY CC.

NM-03179 (WC) et al.
3162.3-1(F) (019)

JAN. 0 4 1990

Meridian Oil Incorporated
P. O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells.

- ✓ 1. No. 700 Aztec, 810' FSL & 790' FWL, sec. 14, T. 28 N., R. 1² W., San Juan County, New Mexico, lease NM-03179.
2. No. 103 Hubbard Com, 1930' FNL & 1490' FEL, sec. 22, T. 32 N., R. 11 W., San Juan County, New Mexico, lease SF-078312.
3. No. 101 Hubbard Com, 790' FSL & 2115' FWL, sec. 15, T. 32 N., R. 12 W., San Juan County, New Mexico, lease SF-078312.
4. No. 100 Hubbard, 1000' FSL & 790' FWL, sec. 11, T. 32 N., R. 12 W., San Juan County, New Mexico, lease SF-078312.
- ✓ 5. No. 707 Hancock, 1705' FSL & 1550' FWL, sec. 23, T. 28 N., R. 9 W., San Juan County, New Mexico, lease NM-04209.
6. No. 296 Hare, 1450' FNL & 1565' FEL, sec. 23, T. 29 N., R. 10 W., San Juan County, New Mexico, lease SF-076958.

The subject APDs are rescinded and returned pursuant to your written instructions dated November 29, 1989.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment of liquidated damages.

Sincerely,

ABANDONED LOCATION

John L. Keller
for John L. Keller
Chief, Branch of Minerals

6 Enclosures

cc:
NMOCD, Aztec

RECEIVED

JAN 08 1990

OIL CON. DIV.
DIST. 3