UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sunary Noti	ces and Reports on Wells	. 44	
			1310N, NSI	Lease Number NM-58887
Type of Well GAS		JUN 2000	6.	If Indian, All. or Tribe Name
			7.	Unit Agreement Nam
Name of Oper	rator			
RESOL	NGTON OIL	GAS COMPANY		
			8.	Well Name & Number Newco #100
Address & Pl	hone No. of Opera	87499 (505) 326-9700	9.	API Well No.
			10	30-045-26995 Field and Pool
Location of	Well, Footage, S	ec., T, R, M T_32_N R-9-W NMPM	10.	Basin Fruitland Co
1630'FSL, I	640 FWL, Sec.20,	T-32-N, R-9-W, NMPM	11.	County and State
				San Juan Co, NM
. CHECK APPR	OPRIATE BOX TO IN	DICATE NATURE OF NOTICE,	REPORT, OTH	ER DATA
Type of Sub	mission	Type of Acti	on Change of P	
Not	ice of Intent	Recompletion	New Constru	iction
x Sub	sequent Report	Plugging Back	Non-Routine	Fracturing
^	Dog. Company	Casing Repair	Water Shut	oti
	-1 Abandonmont	Altering Casing	Conversion	to injection
Fin	al Abandonment			
Fin	al Abandonmenc	X Other - Recavitation	<u> </u>	
	Proposed or Comp	X Other - Recavitation	1	
	Proposed or Comp	X Other - Recavitation	SDON.	
. Describe	Proposed or Comp MIRU. TOOH w/pur TOOH w/2 3/8" th	X_ Other - Recavitation Dleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger	SDON.	
5-7-00 5-8-00	MIRU. TOOH w/pur TOOH w/2 3/8" th	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON.	SDON.	e. TOOH w/9 jts 5 ½
5-7-00 5-8-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow	X Other - Recavitation X Other - Recavitations X Other - Recavitations	SDON. S & pull fre	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I
5-7-00 5-8-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. Si TIH w/bit. Blow Blow well. CO to csg, set @ 3	X Other - Recavitation Coleted Operations The prodest ND WH. NU BOP. The prodest ND	SDON. C & pull fre TIH w/10 jt c pre-perf @	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. Si TIH w/bit. Blow Blow well. CO to csg, set @ 3	X Other - Recavitation Coleted Operations The prodest ND WH. NU BOP. The prodest ND	SDON. C & pull fre TIH w/10 jt c pre-perf @	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 L 3321-63', 3385-340
5-7-00 5-8-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Ln: cross coal interval. SDON Mill perf plugs@ 3321-6	SDON. Solution & pull free TIH w/10 jt r pre-perf @ 3', 3385-340	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill. w/perf mill. TIH w/115 its 2	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 SDON. 3/8" 4.7# J-55 tbg, set	SDON. E & pull fre TIH w/10 jt r pre-perf @ 3', 3385-340 @ 3593'. ND	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill. w/perf mill. TIH w/115 its 2	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Ln: cross coal interval. SDON Mill perf plugs@ 3321-6	SDON. E & pull fre TIH w/10 jt r pre-perf @ 3', 3385-340 @ 3593'. ND	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill. w/perf mill. TIH w/115 its 2	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 SDON. 3/8" 4.7# J-55 tbg, set	SDON. E & pull fre TIH w/10 jt r pre-perf @ 3', 3385-340 @ 3593'. ND	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill. w/perf mill. TIH w/115 its 2	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 SDON. 3/8" 4.7# J-55 tbg, set	SDON. E & pull fre TIH w/10 jt r pre-perf @ 3', 3385-340 @ 3593'. ND	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00 5-25-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill w/perf mill. TIH w/115 jts 2 & rods. PT &	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 sDON. 3/8" 4.7# J-55 tbg, set pump action, OK. RD. Rig	SDON. TEM w/10 jt pre-perf @ 3', 3385-340 3593'. ND released.	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00 5-25-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill w/perf mill. TIH w/115 jts 2 & rods. PT &	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 SDON. 3/8" 4.7# J-55 tbg, set	SDON. TEM w/10 jt pre-perf @ 3', 3385-340 3593'. ND released.	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 I 3321-63', 3385-340
5-7-00 5-8-00 5-9/22-00 5-23-00 5-25-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill w/perf mill. TIH w/115 jts 2 & rods. PT &	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 sDON. 3/8" 4.7# J-55 tbg, set pump action, OK. RD. Rig	SDON. The word of the pre-perf @ 3', 3385-340 3593'. ND released.	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 L s 3321-63', 3385-340 s7', & 3553-95'. TOOM BOP. NU WH. TIH w/g
5-7-00 5-8-00 5-9/22-00 5-23-00 5-25-00 5-26-00	MIRU. TOOH w/pur TOOH w/2 3/8" th 15.5# csg. SI TIH w/bit. Blow Blow well. CO to csg, set @ 3 & 3553-95' a TIH w/perf mill w/perf mill. TIH w/115 jts 2 & rods. PT &	X Other - Recavitation pleted Operations mp & rods. ND WH. NU BOP. og. TIH, engage lnr hanger DON. well & CO. o TD @ 3598'. TOOH w/bit. 597'. Lnr top @ 3332'. Lnr cross coal interval. SDON . Mill perf plugs@ 3321-6 sDON. 3/8" 4.7# J-55 tbg, set pump action, OK. RD. Rig	SDON. The will free the pre-perf of the perf	e. TOOH w/9 jts 5 ½ s 5 ½" 15.5# K-55 L 3321-63', 3385-340 7', & 3553-95'. TOOK BOP. NU WH. TIH w/p