

F


30-039-23116

11-12-82

F. Loc. 870/E; 330/S Elev. 7042 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @
Csg. Perf. Prod. Stim.T
R
A
N
S

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. Ist Del. s

TOPS		NITD X	Well Log	TEST DATA						
Kirtland		C-103	Plot X	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104	Electric Log							
Pictured Cliffs			C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout										
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										

40

P
o
o

Lybrook/Gal Co. RA S 31 T 24N R 7W UP Oper Flag Redfern Oil Co. Lse. Betty "C" 31 No. 7

BETTY "C" 31 #7

P-31-24N-7W

Flag Redfern Oil Co.



IN REPLY REFER TO:

3100 (016)

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Caller Service 4104
Farmington, New Mexico 87499

CERTIFIED

UNC Texas, Inc.
P. O. Drawer 1311
Midland, Texas 79702JHH ☐
GSB
(BHG)
RMG
ENG
GEO
L&E
ACCT.

JJR



MAY 29 1984


23 MAY 1984

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 7 Betty 'C' 31, SE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 31, T. 24 N., R. 7 W., Rio Arriba County, New Mexico, lease New Mexico-014023. The subject APD is rescinded and returned due to drilling not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,


Area Manager
Acting

Enclosure

ABANDONED LOCATION

RECEIVED
AUG 28 1989
OIL CON. DIV.
DIST. 3