5-USGS (Farmington) 1-File	1 4
Form 9-331 INITED STATES SUBMIT IN TRIPLICATES	Form approved.
(May 1963)  DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)	Badget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	NM /0206995
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	
1. OIL GAS C	7. UNIT AGREEMENT NAME
we'l well other Mistake  2. NAME OF OPERATOR	8. FARM OR LEASE NAME.
Thomas A. Dugan	Aztechia
3. ADDRESS OF OPERATOR	9. WELL NO.
Box 234, Farmington, NM 87401	1 #### 1 88mm = 1 88mm = 1 8 mm = 1 8 m
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
At surface	Wildcat
890' FNL - 890' FWL	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARBA
	$\mathbf{Sec}^{\frac{1}{2}}\mathbf{\tilde{S}}^{\frac{1}{2}}\mathbf{\tilde{T}}30\mathbf{N}^{\frac{1}{2}}\mathbf{\tilde{R}}^{\frac{1}{2}}\mathbf{\tilde{A}}\mathbf{\tilde{W}}^{\frac{1}{2}}\mathbf{\tilde{\tilde{G}}}^{\frac{1}{2}}$
14. PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
5584' GR	San Juan NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data 3 5 5 5 5 5 5
	ENT REPORT OF
	1 3343 8 5 <del>14</del> 6
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF  FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING WELL
SHOOT OR ACIDIZE ABANDON* X SHOOTING OR ACIDIZING	ABANDON MENT*
REPAIR WELL CHANGE PLANS (Other)	
(Other) (Note: Report results Completion or Recompl	of multiple completion on Well etion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical	including estimated date of starting any l depths for all markers and zones perti-
nent to this work.) *	그 의 표현폭발 한 원니크는 166
Plan to plug and abandon well.	a grava i grava en
	the college
1. Plan to spot 10 sx cement 735 to 635'.	୍ ଓ ବିଷ୍ଟିତ ନି ବ୍ୟସ୍କ
2. Plan to spot 5 sx cement 50' to surface.	
2. Fian to spot 3 sa coment 30 to surrace.	og of afres layer for a document of document of ared end, the stropper of type for a dress and the dress ared ared ared ared ared
3. Plan to cut off 4-1/2" csg and surface csg.	of afra- or mode a drock a drock a drock a drock a drock a drock d drock drock drock drock drock drock drock
	of of allowers of the oral formal of the mal formation to another in allowers from the case of the cas
4. Clean up location.	Fox (196 2 the 19 2 the 19 2 the 19 2 the 19 2 the 19 2 the 19 2 the 19
	opore and the land the land to the land to the land to the land of the land to
5. Abandon Location.	
& Install dry hole marker	
	1 BEEFE AFO
	The partial of the pa
NOT THE STATE OF T	the second secon
	MISS GEOLUGIO ESTREY
18. I hereby certify that the foregoing is true and correct	DATE 4-27-78
SIGNED THE Petroleum Engineer	DATE 4-27-78
Thomas A. Dugan (This space for Federal or State/office use)	
APPROVED BYTITLE	DATE DATE
CONDITIONS OF APPROVAL, IF ANY:	

\*See Instructions on Reverse Side

What