




STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 8, 1993

Ms. Susan Dolan
Meridian Oil Incorporation
P. O. Box 4289
Farmington, NM 87499

Re: Southland Royalty Co. East ^{1CM}~~1~~-M N-26-31N-12W
Southland Royalty Co. Thompson #2 C-28-31N-12W

Dear Susan:

As the enclosed copies of the 1993 Bradenhead Test reports indicate, the referenced wells were not tested because the Bradenheads were bullplugged. A review of past tests show the wells were tested in 1990. You are hereby directed to remove the bullplugs and test the wells prior to January 1, 1994.

Also, our records indicate the Thompson #2 has intermediate casing. The wellhead must be dug out to expose the Bradenhead spool, and the well tested properly.

Yours truly

Charles Gholson
Deputy Oil & Gas Inspector

CG/ej

Enclosure

xc: well files